

Preface

Thanks a lot for purchasing our total station!

This manual is your good helper, please read it carefully before using the instrument and keep it safely.

Product affirms:

In order to get the best service from our company, please feedback your instruments' version including number, purchasing date and your suggestions to us after the purchasing of the product.

We will attach great importance to any piece of advice from you, We will be very concerned about any detail of our products, We will make great efforts to provide better quality.

Notice: Our Company has the right to upgrade and improve the technical parameters of instruments, which may not be announced in advance .The pictures in the manual are only for reference and kind prevail.

Features:

Rich Feature: Our Total Station is equipped with a wealth of measurement applications including data storage, parameter settings and etc. It's suitable for all kinds of professional measurements.

1. Absolute coded dial

With absolute digital dial, instruments can be measured directly when it powers on. The measured azimuth angle result will not be lost even when the instrument shut off.

2. powerful memory management

Large-capacity EMS memory, easy to manage the file system, serving to add, delete and transfer data.

3. No prism ranging

The series Total Station with laser ranging No-Prism is capable of surveying for long distance, fast and precise measurements with various materials and different colors of objects (such as building walls, poles, wires, cliff wall, mountain, mud, stakes, etc.). For those which are hard or impossible to be reached, the application of Prism features can be a good measurement tasks.

4. special measurement procedure

The series total station is equipped with the basic surveying function as well as special measurement procedures, undertaking REM, offset measuring, stakeout, Resection, area measurement and calculation, road design etc. to meet the needs of professional measurement.

5. eyepiece changeable

The instruments' eyepiece can be changed, and equipped with a diagonal eyepiece, serving to observe zenith and high buildings.

6. An optional laser plumb

The site features is easy to instruct and set up stations.

NOTE:

- 1. Avoid look directly into the sun with the eyepiece when measuring. Recommended to use solar filter to reduce the impact.
- 2. Avoid extreme temperature when storing equipment and sudden changes in temperature when using the instrument.
- 3. The instrument should be loaded in box placed in dry and ventilated place and prevented from shock, dust and moisture when it is not in use.
- 4. In order to get good accuracy, you should leave the instrument in the box if the instrument temperature has large difference between working and storing you may unpack the box and employ the instrument until the instrument reaches the temperature at the working field.
- 5. If the instrument is not used for a long time, the battery should be unloaded and stored separately and charged once a month to prolong battery life.
- 6. The instrument should be installed in box when it is transported. Extrusion, collision and violent vibration need to be carefully avoided during the transport process. The soft mat May be placed around the box on the long-distance transportation.
- 7. It is better to use high quality wooden foot stool to make sure the stability of measurement and improve its accuracy, when setting up the instrument.
- 8. Only use absorbent cotton or lens paper to wipe the instrument gently if exposed optical device need to be cleaned.
- 9. Use flannelette or hairbrush to clean the instrument after using. Do not electrify and start up after the device got wet in a rain. Using clean soft cloth to wipe it dry and put it at ventilated place for a period of time to make the instrument fully dry before using or packing.

- 10. Inspect instrument carefully and comprehensively to ensure its indicators, function, power supply, initial setting and correction parameters meet the requirements before operating.
- 11. If the function is abnormal, non-professional maintenance persons are not allowed to dismantle the device without authorization in case of any unnecessary damage.
- 12. The emitted light of the no-prism total station is laser, do not direct to eyes.

Security Guide

Pay attention to the following safety matters when you use the laser ranging free of prism.

Warning:

Total station fit out laser level 3R/IIIa which is recognized by the loge, which is above:

the vertical locking screw saying: "3A laser product ".This product belongs to Class 3R level laser .According to the following standards IEC 60825-1: 2001Class 3R/IIIa laser product can reach five times of emission limits of the Class 2/II in the wavelength between 400nm-700nm.

Warning :

Continuous stare into the laser beam is harmful.

Prevention:

Do not stare at laser beam or point to others. The reflected beams is the effective signal of the instrument. It's safety to observe by eyepiece.

Warning:

When the laser beam is irradiated reflected by prisms, plane mirrors, surface of metal and windows, it's dangerous to look straight into the reflected beams.

Prevention :

Don't stare at the reflected beams. When the laser is switched on (distance mode), do not obstruct optical path or stand near the prism. Target at a prism with total station telescope only.

Warning :

It's dangerous to use the Class 3R laser device improperly.

Prevention:

To avoid injury, each user must carry safety prevention measures and operate the instrument within the safety scope according to standard IEC60825-1: 2001).

The following is the explanation of the main part of the standard:

Class 3R level laser products are used outdoors and in construction (surveying with No-Prism).

A: Only trained and certified persons are allowed to install, adjust and operate the laser equipment.

B: Set up appropriate laser warning sign within the operating field

C: To prevent anyone from looking into the laser beam use an optical instrument to observe.

D: In order to prevent laser damage to persons, the laser beams should be blocked at the end of the working route, and also should be cut off when people work in the restricted area (harmful distance)where laser beams crossing are harmful.

E: The route of the laser beam must set to be higher or lower than the human eye.

F: Properly store and safe keep the laser products when they it is not used, unauthenticated personals are not allowed using it.

G: Do not point laser beams at surfaces such as plane mirror, metal surface, window, especially the surface of plane mirror and concave mirror.

Harmful Distance is the maximum distance from the starting point of the laser beams to where people are right safe. The built-in harmful distance of the Class 3R/IIIa laser is 1000m(3300ft) and the laser intensity will reduce to that of Class 1 products (which does not harm eyes) if people is out of this range.

1 Name and function of each part 1 -	-
1.1 Name 1 -	-
1.2 Keys Functions and information display 2 -	-
2 Preparation before measurement 4 -	-
2.1 Unpack and store instrument 4 -	-
2.2 Setting up the instrument 4 -	-
2.3 About the battery7 -	5
2.4 Reflecting prism8 -	-
2.5 Loading or unloading the base	-
2.6 Adjust telescope objective and aiming target	-
2.7 Input Mode 10 -	-
2.7.1 Input characters 11 -	-
2.7.2 Delete characters 13 -	-
2.8 Point Search 14 -	-
2.8.1 Direct search	-
2.8.2 Wildcard search 19 -	-
3 Q-Survey 20 -	-
3.1 Notes in the distance measurement 20 -	-
3.2 EDM Setting 22 -	-
3.2.1 Set the mode of EDM 22 -	-
3.2.2 Atmosphere setting 26 -	-
3.2.3 Grid factor setting 30 -	-
3.2.4 EDM signal 32 -	-
3.3 Start measurement 33 -	-
3.3.1 Set HA 34 -	_

Content

3.3.2 Set Station and instrument height 37 -
3.3.3 Measurement 39 -
3.3.4 Code 40 -
4 Functions 44 -
4.1 Level 45 -
4.2 Offset 45 -
4.2.1 Distance Offset 46 -
4.2.2 Cylinder Offset 48 -
4.2.3 Angel Offset 50 -
4.3 NP/P Toggle 54 -
4.4 Height Transfer 55 -
4.5 Hidden Point 60 -
4.6 Free Coding 63 -
4.7 Laser Pointer 63 -
4.8 Light 64 -
4.9 Unit Setting 64 -
4.10 Main Setting 65 -
4.11 EDM Tracking 65 -
5 Applications 67 -
5.1 Setting the Job 67 -
5.1.1 Create a new Job 67 -
5.1.2 Select an Existing Job from Memory 69 -
5.2 Setting the Station 71 -
5.2.1 Select the coordinate from memory [Find] 71 -
5.2.2 Select the Fix Point in the Memory [List] 75 -
5.2.3 Input the coordinates manually 77 -

5.3 Setting the Orientation 79 -
5.3.1 Manual input orientation 79 -
5.3.2 Set orientation with coordinates 81 -
5.4 Starting the Applications 86 -
5.5 Surveying 87 -
5.5.1 Individual Point 90 -
5.5.2 Data 91 -
5.6 Stakeout 98 -
5.6.1 Set Stakeout Point 99 -
5.6.2 Polar Stakeout Mode 105 -
5.6.3 Orthogonal to Station Stakeout Mode 109 -
5.6.4 Cartesian Stakeout Mode 114 -
5.6.5 Polar 118 -
5.7 Resection 123 -
5.8 Tie Distance 127 -
5.8.1 Polygonal 128 -
5.8.2 Radial 133 -
5.9 Area 138 -
5.10 Remote Height 142 -
5.10.1 Prism High Unknown 144 -
5.11 COGO 148 -
5.11.1 Traverse 148 -
5.11.2 Inverse 153 -
5.11.3 Bearing-Bearing Intersection 157 -
5.11.4 Bearing-Distance Intersection 160 -


5.11.6 Line-Line Intersection 167 -	-
5.11.7 Distance-Offset 169 -	-
5.11.8 Set Point 172 -	-
5.11.9 Extension 174 -	-
5.12 Road 177 -	-
5.12.1 Road Manage 178 -	-
5.12.2 HC list 179 -	-
5.12.3 Vert.curve list 187 -	-
5.12.4 Road Stakeout 190 -	-
5.13 Stakeout Reference Element 191 -	-
5.13.1 RefLine 192 -	-
5.13.2 RefArc 209 -	-
5.13.3 RefSurface 236 -	-
6 File manage 239 -	-
6.1 Job 239 -	-
6.1.1 Select a Job 240 -	-
6.1.2 New a Job 241 -	-
6.1.3 Delete a job 243 -	-
6.2 Fix Pt 244 -	-
6.2.1 Search Fix Pt 246 -	-
6.2.2 Add Fix Pt 247 -	-
6.2.3 Edit Fix Pt 250 -	-
6.2.4 Delete Fix Pt 251 -	-
6.3 Meas. Pt 253 -	-
6.3.1 View the measurement data 253 -	-
6.3.2 Delete measurement data 255 -	

6.4 Code 256	j -
6.4.1 Input Code 257	-
6.4.2 View Code 259	- 1
6.4.3 Delete Code 261	-
6.5 Memory Statistics 262	2 -
7 Data Transfer 264	-
7.1 Data Import 264	
7.2 Data Export 270	- 1
8 Instrument Setting 274	-
8.1 General Setting 274	
8.2 EDM Setting 280) -
9 Adjust and Tools 281	-
9.1 Adjust 281	-
9.1.1 View adjust parameters 282	. –
9.1.2 Adjust Index Error 283	-
9.1.3 Adjust Tilt X 284	
9.1.4 Adjust Tilt <mark>Y</mark> 287	-
9.1.5 Adjust Tilt Zero 290) -
9.1.6 Adjust Haxis err 291	-
9.1.7 Adjust collimate err 293	i -
9.1.8 Instrument constant setting 295	i –
9.1.9 Factory setting 295	i –
9.2 System information 295	i –
9.2.1 View System Information 295	i –
9.2.2 Set System Date 296	; -
9.2.3 Set System Time 296	j -


9.2.4 Firmware Upgrade 297 -
9.3 Checkout and calibration 300 -
9.3.1 Tube level 301 -
9.3.2 Circular level 302 -
9.3.3 Telescope reticle 302 -
9.3.4 The verticality of collimation axis and horizontal axis(2C)- 303 -
9.3.5 Vertical plate index zero automatic compensation 305 -
9.3.6 Vertical collimation error (I Angle) and vertical collimation
zero value setting 306 -
9.3.7 Plummet 306 -
9.3.8 Instrument additive constant (K) 308 -
9.3.9 The parallelism of collimation axis and photoelectricity axis- 309 -
9.3.10 No prism ranging 310 -
10 Technical parameters 311 -
11 Attachment A File transfer format description (local format) 314 -

1 Name and function of each part

1.1 Name



1.2 Keys Functions and information display



Key	Function				
	Power ON/ Power OFF.				
MEAS	Frigger key, depends on setting, maybe disting& save, disting or none.				
ESC	Cancel or exit.				
ENT	Confirm <mark>or c</mark> ommit editing.				
	Page turning				
FNC	Hot key to enter function menu in measuring interface.				
R 1	User defined function key 1.				
82	User defined function key 2				
	Move cursor up or go to previous.				
•	Move cursor down or go to next.				
	Move cursor left or go to left.				
•	Move cursor right or go to right.				
STU GHI	Entering letters A-Z.				

1~9		
0~9	Entering number or choose menu item.	
F1 ~ F4	F1 ~ F4 Soft keys to choose screen bottom function.	
	\odot	

2 Preparation before measurement

2.1 Unpack and store instrument

• Unpack

Put down the box gently and turn up the cover then turn on the lock, open the cover and take out the instrument.

• Deposit

Cover up the telescope mirror and make the vertical motion of alidade upwards then put the instrument horizontally (keep the objective upwards) into box. Then screw vertical motion gently. Cover up the box cover and lock the box. Loose horizontal and vertical axis as much as possible to reduce the shock damage to instrument.

2.2 Setting up the instrument

Install the instrument onto the tripod gently, then level and center the instrument to ensure the accuracy of the measurement result.


• Reference for operation:

1. Centering and levelling


- 1) Set up the tripod
 - Position tripod legs so that the plummet is aimed to the ground mark point. Turn the focusing ring of the optical plummet to focus;
 - ② Make sure that the center of the tripod top is right above the station;
 - ③ Stamp the tripod on the ground with your feet.
- 2) Install the instrument onto the tripod

Mount the instrument on the tripod head. Support it with one hand, and tighten the centering screw on the bottom of the unit to make sure it is secured to the tripod.

- 3) Using the circular level to level the instrument coarsely
 - Twist and adjust the two leveling screw A and B on the bottom of the instrument until the bubbles of the circular level moves to the line perpendicular to the center line the screw A and B;
 - ② Twist and adjust leveling screw C to move the bubble to the center of the circular level.




- 4) Using the plate level to level the instrument precisely
 - (1) Loosen the horizontal locking screw and turn the instrument around until the plate level is perpendicular to a line shaped with screws A and B. Adjust the screws A and B to make the bubble in the center of the level;



2 Turn the instrument approximately 90° and adjust screw C until

the bubble in the center of the level;



③ Turn around the instrument 90° again. Repeat above steps until the bubble remains in the center of the plate level even though the instrument is rotated to any position.

2. Centering by centering tool (optional or laser)

1)Set up a tripod

Extend a tripod to the appropriate height make sure the legs are spaced at equal intervals and the head is approximately level .Set the tripod so that the head is positioned over the surveying point. Brace tripod on the ground and keep one leg fixed.

2)Set up instrument and spotting

Put instruments on a tripod carefully, and tighten the center connection screw. Adjust the optical centering tool to make reticule clear (open instrument and laser centering if it's a laser centering tool).Handle another two unfixed legs, and adjust their position through the observation of the optical plummet. Make the three legs of the tripod fixed on the ground when the optical plummet is aligned to the station approximately .Adjust three feet screws of total station and keep the optical centering tool (or laser centering) aiming at the station accurately.

3)Leveling instrument roughly by circular level

(Same as The section above that discusses centering and leveling with plumb bob)

4)Leveling instrument accurately by tubular level

(Same as The section above that discusses centering and leveling with plumb bob)

5)Centering and leveling accurately

Loosen center connection screw slightly and move instrument horizontally(Don't rotate instrument) through observation to optical plummet, making the instrument aim at station accurately. Tighten the center connection screw and leveling instrument accurately again.

This operation should be repeated till the plumb aims at station accurately.

2.3 About the battery

• Mounting the battery

 $rac{1}{3}$ Fully charge the battery before measurement.

rightarrow Cut off the power before removing the battery.

► Step mounting the battery

1. Insert the battery to the instrument.

2. Press the top of the battery until you hear a click sound.

►Step Remove battery

1. Press the button downward.

2. Remove the battery by pulling it toward you.

• Battery information

——Power is adequate, operating available.

The battery can be used for 4 hours when this symbol first appears. If you cannot master the consumed time, you should prepare a spare battery or charge the battery before using.

□ ——End of the operation as soon as possible and replace the

battery and charge if running out of power.

 $\hat{\mathbf{U}}$ ——It takes several minutes for the instrument to shut down when this symbol first appears. The battery has few power now and should be replaced an recharged.

Notice:

- The operating time of battery depends on environmental conditions such as ambient temperature, time and times of charging and so on the battery is suggested to be prepared or charged ahead before operation to keep it safety.
- ② The battery symbol only indicates power capability undercurrent measurement mode. The remained capacity of the battery shown under current mode does not guarantee its capacity under other modes .Because consumption of power in distance measurement mode is more than that in angle measurement mode ,the instrument may end ranging sometimes due to insufficient capacity of battery (when switching between modes).

Notice in charging:

- Though overcharging protection is installed in the instrument, please plug off the battery immediately after finishing charging.
- Charging range from 0°~±45°C. Abnormal responds of instrument occurs over this range.
- Rechargeable for 300—500 times, it may shorten Service time of the battery completely.
- Charge the battery once a month no matter if it is used to prolong its longevity.

2.4 Reflecting prism

When measuring distance with prism mode, a reflecting prism must be set at the target site. You can connect the prism to the base, and then connect the base onto the tripod .you can also set the prism onto the centering rod. There are single-prism group and three prism group available on the market, so you can select them according to your requirements.

2.5 Loading or unloading the base

Loading

Put the three fixed feet in the corresponding bases, make the instrument in a triangular base, clockwise lock the button by 180° to lock the base, and then fix screw with a screwdriver to screw it out at a fixed lock knob.

• Unloading

If necessary, the triangle base can be removed from the instrument (including the same base of reflection prism base connector) by loosening the lock knob base fixed screw with a screwdriver, and anticlockwise locking button about 180° , then separate the instrument from base.

2.6 Adjust telescope objective and aiming target

Aiming method (reference)

① Rotate the telescope and point it to the bright sky and focus reticule clearly (by rotating eyepiece in own direction and focusing reticule slowly).

(2) Aim at the target with the crosswire in optical sight , and keep an appropriate distance when aiming (about 200mm).

③ Use telescope focus screw to make target clear.

It means that focus or eyepiece diopter is not adjusted when there is a parallax with eye moving up and down, thus focus carefully and adjust eyepiece to reduce parallax.

2.7 Input Mode

Total station keyboard includes alpha/digit keys. User can input letters and numbers directly.

• Input box:

Each digit key defines 3 letters and 1 number. Depends on the properties of input box, input process varies.

Number input box:

In number input box, user can only input numbers, include "1-9",".", "-+" Number will appear in box when user presses the key.

Text input box:

In text input box, user can input numbers and letters. Repeat pressing same key to get proper letter, such as A->B->C->7.

When right-bottom of screen display icon ^A, user can input number/letter; when display icon ¹, user can only input number. User can press soft-key [F4] to switch input mode between Number and Text when input box been active.

• Letters:

Letters that total station can input includes "A-Z/ $\ @\&^?!+-$.". When wildcard queries, you need to use the "*" character and press the ± key twice in the character input mode of the total station,.

- Arrow key $| \leftarrow |, \rightarrow |$ move inputting cursor.
- > Pressing ENT enters editing; pressing ENT confirms input after editing.
- > When editing distance, angle, temperature and pressure values that


contain unit format, input box's text will convert into text without unit format. Such as angle $29 \circ 32' 56''$ transforms into 29.3256; Distance 115.321m transforms into 115.321. When finish editing, the text will automatic convert back.

2.7.1 Input characters

Each digit key defines 3 letters and 1 number. In text input mode, each time pressing the key, one character appears at cursor position. Number appears when pressing 4 times.

Example: input 123ABV2


Steps	Key	Display
 Pressing key to start inputting. Right-bottom screen displaying icon 1 means in number input mode. 		[Q-Survey] 1/3 Pt. : 1 T. H. : 1.500m Code : 13° 29' 59" HA : 13° 29' 59" VA : 90° 59' 23" Image: State of the
 (2) Press key 1, key 2, key 3. Then press key F4, active text input mode. Icon LA should appear in right bottom 	[1],[2],[3],[F4]	[Q-Survey] 1/3 Pt. 1 T. H. 1.500m Code 1 HA 13° 29' 59" VA 90° 59' 23" Image: State of the stat



(4) Press key ENT to finish editing, cursor will move down to next input box.	[ENT]	[Q-Sur Pt. T.H. Code HA VA M B.S.	:	13° 90°	123ABV2 1.500m 29'59" 59'23" 10.044m Dig	LA It
2.7.2 Delete characters Delete or clear input characters.					7	

2.7.2 Delete characters

Steps	Key	Display
①Press key ← to move cursor to right side of the character that to be deleted.	t	[Q-Survey] 1/3 Pt. PTT 01V T. H. 1.500m Code Image: Code HA 13° 29' 59" VA 90° 59' 23" A B. S. Clear Digit



2.8 Point Search

Point search is a function used by applications to find measured or fixed points in the jobs.

Point search is limited to a particular job.

If several points meet the search criteria, then the results are ordered according to the date.

2.8.1 Direct search

By entering an actual point number (for example 'A1'), and pressing key SEARCH, all points within the selected job and with the corresponding point number are found.

Steps	Key	Display
(1) Choosing 'Survey' in application menu, then choose function 'Set STA'. Entering point number, for example 'A1', pressing ENT to finish input, then pressing F1 to search.	[F1]	[Set STA] Input STA PT! Station : A1 Find List Coord.
② In searching result window, using arrow key ↑↓ to move cursor to select point number. Press key F4 or ENT to confirm selecting.	↑ +[F4]/ [ENT]	[Find Pt.]1/5A1StationA1StationA1Meas. PTA1Meas. PTA1Meas. PTViewCoord.JobOK

Here is an example for searching fix point in function 'Set STA'.

Soft keys introduction:

[View] Show the coordinate of selected point.

 ③ Using arrow key ↑ ↓ to move cursor and select point number. Press key F1 to show the coordinate details of selected point. 	[F1]	[View Coord.] Job : DEFAULT Pt. : A1 N : 0.000m E : 0.000m Z : 0.000m Date : 2015.05.15 OK
(4) Press ESC or F4 back to previous screen.	[ESC] [F4]	[Find Pt.]1/5A1StationA1StationA1Meas. PTA1Meas. PTA1Meas. PTViewCoord.JobOK

[Coord.] Input point manually.


③ If required point		[Input Coord.]
not exists in the job, user can manually input it by pressing key F2. by pressing ENT to input box.	[F2]	Job : DEFAULT Pt. : 566 N : 0.000m E : 0.000m Z : 0.000m Back OK

		-
(4) Input point number and N, E, Z values, by pressing ENT to move cursor to next input box.	[ENT]	[Input Coord.] Job : DEFAULT Pt. : 566 N : 3.012m E : 15.012m Z : 4.125m Back OK
(5) After all values finishing input, pressing key F4 to save the point to the job.	[F4]	
[Job]Choose another job	s points.	~?
③ If required point not exists in the job, user can choose	[F3]	[Find Pt.] Job : DEFAULT Pt. : 566 Select job or input coord.!

Job

Zero Coord. Find

another job's points.



[OK] Commit selected point.

2.8.2 Wildcard search

The wildcard search is indicated by a "*". The asterisk is a place holder for any following sequence of characters. Wildcards should be used if the point number is not fully known, or to search for a batch of points.

Examples:

* All points are found.

A All points with exactly the point number "A" are found.

A* All points containing "A" are found, for example, A1, A2, 1A.

Steps: (For example "*")

Steps	Key	Display
(1) Choosing 'Survey' in application menu, then choose function 'Set STA'. Entering "*", pressing ENT to finish input, then pressing F1 to search.	[F1]	[Set STA] Input STA PT! Station : A1 Find List Coord.
(2) In searching result window, using arrow key ↑↓ to move cursor to select point number. Press key F4 or ENT to confirm selecting.	↑↓ [F4] [ENT]	[Find Pt.]1/5A1StationA1StationA1Meas. PTA1Meas. PTA1Meas. PTViewCoord.JobOK

3 Q-Survey

3.1 Notes in the distance measurement

After the placement of instrument and turned on the power, total station is ready, can start measuring.

In measurement display, user can call the function of set key, the function keys and hotkey.

The show is an example. Localized version may be slightly different. The example of Q-Survey show:

[Q-Surve	ey] 1/3	3	
Pt.	:	P	Г01V 🗍
Т. Н.	:	1.5	500m 🚖
Code			C P
HA		3° 29′ 5	
VA	: 9	0° 59′ 2	23″
	÷		LA
ALL	DIST	REC	Ļ
ALL	Code	EDM	Ļ
Station	Zero	SetHA	⊬

F1-F4 Start the corresponding functions

Notes:

Measurements to strongly reflecting targets such as to traffic lights in Reflector EDM mode without prism should be avoided. The measured distances may be wrong or inaccurate.

When a distance measurement is triggered, the EDM measures to the object which is in the beam path at that moment.

If e.g. people, cars, animals, swaying branches, etc. cross the laser beam while a measurement is being taken, a fraction of the laser beam is reflected and may lead to incorrect distance values.

Avoid interrupting the measuring beam while taking reflector less measurements or measurements using reflective foils.

- No Prism Ranging
- Ensure that laser beam is not reflected by any object with high reflectivity and close to the light path.
- When start the distance measurement, EDM will measure distance for the object in the light path. If there are temporary obstacles in the light path (such as by car, or the heavy rain, snow, or filled with fog), the distance measured by EDM is the distance to the nearest obstacle.
- When a long distance measurement, laser beam deviation of collimation line will affect the accuracy of measurement. This is because the divergence of the laser beam reflection point may not be with the crosshair sighting points coincide. It is recommended that the user accurately adjust to ensure that is consistent with laser beam collimation.(Please refer to "20.10 NO Prism Ranging" in the Chapter 9)
- Don't use two instruments to measure the same target at the same time .
- Red light cooperates with reflective pieces to measure distance Laser can also be used to measure distance for reflective pieces. To guarantee the accuracy of measurement, the laser beam is perpendicular to the reflector plate, and through accurate adjustment.(Please refer to "3.10 NO Prism Ranging" in the Chapter 9)

Ensure proper additive constant of different reflection prism.

3.2 EDM Setting

3.2.1 Set the mode of EDM

Select the mode of distance measurement, there are 6 modes : Single,Repeat,Tracking,3 Times,4 Times,5 Times.

Steps	Key	Display
 Press [F4](↓) and show the second soft key in the Q-Surveying. Press [F3] to enter the interface of EDM Setting. 	[F4] [F3]	[Q-Survey] 1/3 Pt. . Pt. . T. H. . Code . HA . 13° 29' VA . 90° 59' ALL Code EDM ↓
(2) When the cursor is in EDM mode option, Press the direction key of $\leftarrow \rightarrow$ to select the mode of measurement. Each time you press \leftarrow or \rightarrow , the mode of measurement is switched.	¢ ↑	[EDM Setting] EDM Mode : Tracking ↓ Reflector: Non-Prism ↓ P.C. 0mm ATMOS Pointer 0K


3 After finishing		
setting, press [F3](OK) to return the function of Q-Surveying. If you want to cancel the settings, press [ESC] to ignore the	[F3]	Setting saved!
changes.		

Set the reflector type

Our series total station can be set up for the red laser (RL) range and invisible infrared light (IR) range and the total station has three reflectors to be selected, which are prism, non-prism (NP) and reflect board (Sheet). You can set by job,but the prism used should be matched with prism constants.

About the parameters of various reflectors in distance measurement, please refer to "Technical Parameters".

Steps	Key	Display
(1) After entering to the interface of EDM Setting, using the direction of \downarrow to move the cursor to the setting item of Reflector.	Ţ	[EDM Setting] EDM Mode : Tracking ↔ Reflector: Non-Prism ↔ P.C. 0mm ATMOS Pointer 0K



Set up the Reflecting Prism Constant.

As a prism is selected as a reflector, a prism constant should be set before any measurement. If the constant is entered and set, it is saved and will not be erased after switching off the instrument.

Example: Prism Constant is -30mm

		Steps		Key	Display
--	--	-------	--	-----	---------

2 0 m " " " " " " " " " " " " " " " " " "

 $\%^2$: The range of Prism constant value: -99mm~+99mm.

Prism.

3.2.2 Atmosphere setting

Refraction:

When measuring horizontal distance and elevation, our instrument corrects the atmospheric refraction and the earth curvature automatically.

The instrument supports of atmospheric refraction coefficient have three option, they are 0.00, 0.14, and 0.20.

Note: The refraction of instrument has been set for K=0.00 when left factory. It also can be set to other values

Steps	Key	Display
(1) After entering to the interface of EDM Setting, press [F1] (Atoms) to enter the interface of Atmospheric Data.	[F1]	[EDM Setting] EDM Mode : Single ↔ Reflector: Non-Prism ↔ P.C. : 0 mm ATMOS Pointer OK ↓
(2) Interface displays the current setting, using the direction of \downarrow to move the cursor to the setting item of Refraction. Press $\overleftarrow{}$ to select the	↓ + ←→	[Atomspheric Data]Temp.:20.0°CPress.:1013hPaPPM:0.0 PPMRefraction::0.00 ↔PPM=0AutoOK

value of refraction. Each time you press $reformed refraction$, the value of refraction is switched.		®
 ③ After finished setting, press [F4] (OK) to save settings and back to previous menu. If you want to cancel the settings, press [ESC] to ignore the changes 	[F4]	[EDM Setting] EDM Mode : Single ↔ Reflector: Non-Prism ↔ P.C. : Omm ATMOS Pointer OK ↓

Atmospheric Correction:

When measuring distance, the measured value will be influenced by the atmosphere.

In order to reduce the influence, a atmospheric correction parameter is needed.

Correction value associated with the pressure and temperature in air. Calculated as follows:

 $PPM = 277.8 - (0.2900* \text{ the air pressure}(hPa))/(1 + 0.00366* \text{ temperature}(^{\circ}C))$

If the air pressure unit is mmHg, Make a conversion according to the

formula:

1hPa=0.75mm Hg

- Standard meteorological conditions (atmospheric correction value =0): press: 1013hPa temperature: 20°C
- > If the atmospheric correction is not required, please set PPM to zero.

Steps	Key	Display
(1) After entering to the interface of EDM Setting. Press [F1] (Atoms) to enter the interface of Atmospheric Data.	[F1]	[EDM Setting] EDM Mode : Single ↔ Reflector: Non-Prism ↔ P.C. : Omm ATMOS Pointer OK ↓
(2) Interface displays the current settings.	Ţ	[Atomspheric Data]Temp.:20.0℃Press.:1013hPaPPM:0.0 PPMRefraction:0.00 ◆PPM=0AutoOK

(3) Input the value of temperature. example: Enter 26°C and press the key of [ENT]. The cursor moves to the setting item of Press.	[ENT]	[Atomspheric Data]Temp.:20.0°CPress.:1013hPaPPM:0.0 PPMRefraction::0.00 ♦PPM=0AutoOK
(4) Input the value of atmospheric pressure. example: Enter 1020 hPa and press the key of[ENT].Program calculates the value of PPM and the cursor moves to the setting item of PPM.% ¹ % ² % ³ % ⁴	[ENT]	[Atomspheric Data]Temp.:20.0°CPress.:1013hPaPPM:3.7PPMRefraction:0.00 ♦PPM=0AutoOK
(5) After finishing setting, press [F4](OK) to save settings and back to previous menu. Then press the key of [F3](OK) to save the setting of EDM and back to the function of measurement.	[F4] [F3]	[Atomspheric Data]Temp.:20.0℃Press.:1013hPaPPM:0.0 PPMRefraction:0.00 ♦PPM=0AutoOK

%1: The range of enter: Temp.(-30°C ~ 60°C), Press.(500hPa~1400hPa).

 \approx 2: The instrument calculates the value of PPM according to the values of temperature and pressure you enter.

※3: Press [F1](PPM=0) can set the value of PPM to 0.

%4: If instrument supports temperature pressure sensor, you can press [F2] to receive the values of air pressure, temperature and calculate the correction value automatically.

3.2.3 Grid factor setting

When calculating the coordinates, the horizontal distance measured must multiply by the scale factor.

Computation formula

```
1.Altitude factor=R/(R+ELEV)
```

R: The average radius of earth

ELEV: mean sea level altitude

2.Scale factor

Scale factor: Scale factor of the station

3.Grid factor

Grid factor=altitude factor × scale factor

Distance calculation

1. Grid distance

 $HDg=HD \times grid factor$

HDg: Grid distance

HD: Ground distance

2. Ground distance

HD=HDg/(Grid factor)

Note:

1. The enter range of the scale factor: 0.99~1.01,the default value is 1.0.

2. The enter range of the average height above sea level: -9999.9999~9999.9999. The average altitude retained after the decimal point one, the default value is 0.

Steps	Key	Display
(1) After entering to the interface of EDM Setting, press the key of [F4] to enter the second page of soft key, then press the key of [F1](Grid) to set the Grid Scale.	[F4] [F1]	[Atomspheric Data]Temp.:20.0℃Press.:1013hPaPPM:0.0 PPMRefraction:0.00 PPM=0AutoOK
(2) Interface displays the current setting. Enter the values of Scale and Altitude then press the key of [ENT].Program calculates the Grid Scale and displays it in the interface. If you want to set all enter area to 0,you	[ENT]	[Grid Scale] Scale : 1.0000 Altitude : 0.000m Grid Scale: 1.0000 Reset OK

can set the key of [F1] (Reset).		
③Afterfinishedsetting, press[F4](OK)to save settings and backto previous menu. Thenpressthekey[F3](OK)tosavesetting of EDM and backtothefunction	[F4]	[EDM Setting] EDM Mode : Single ↔ Reflector: Non-Prism ↔ P.C. : Onnm ATMOS Pointer OK ↓
measurement.		

3.2.4 EDM signal

The function of signal is to display the intensity of signal received by total station. If the target is hard to be found or can't see, using the function can achieve the best sighting accuracy.


Steps	Key	Display
(1) After entering to the interface of EDM Setting, press the key of [F4] to enter the second page of soft key, then press the key of [F2](Signal) to enter the	[F4] + [F2]	[EDM Setting] EDM Mode : Single ↔ Reflector: Non-Prism ↔ P.C. Omm ATMOS Pointer OK

function of Signal intensity.		
(2) Using the bar chart and value of number to show the intensity of signal received by total station in the screen. As shown in the picture on the right.		[EDM Signa1] Strenght : 50% Back
③ Press [F1] or [ESC] to back to the menu of EDM setting.	[F1] or [ESC]	[EDM Setting] EDM Mode : Single ↔ Reflector: Non-Prism ↔ P.C. Omm ATMOS Pointer OK

3.3 Start measurement

Q-Survey has 3 pages menu, including all measuring functions commonly used, such as angle measurement, distance measurement and coordinate measurement.

As shown below:



3.3.1 Set HA

You can set the horizontal angle as 0 or set it as wanted angle.

Set	horizontal	anole	to	0.
BUL	norizontai	angic	ιU	v.


Steps	Key	Display			
(1) Aim at the target which used to orient. Press [F4] twice to enter third pages soft key.	[F4] + [F4]	[Q-Surve Pt. T.H. Code HA VA ▲ ALL ALL Station	:	P' 1. 5	F01V 500m 59″ 23″ ↓ ↓ ↓

(2) Press [F2](Zero), the screen give a prompt to set HA as 0 or not.	[F2]	Set HA=0? No Yes
(3) Press [F4](Yes), the screen backs to Q-Survey and HA is set as 0. If you want to cancel the operation, please press [F1](No).	[F4] or [F1]	[Q-Survey] 1/3 Pt. 123ABV2 T. H. 1.500m Code 13° 29' 59" HA 13° 29' 59" VA 90° 59' 23" I. 10.044m ALL DIST

Set HA.

Steps	Key	Display

(1) Aim at the target which used to orient. Press [F4] twice to enter third pages soft key.	[F4] + [F4]	[Q-Survey] 1/3 Pt. : PT01V T. H. : 1.500m Code : . HA : 13° 29' 59" VA : 90° 59' 23" ▲ : . ALL DIST REC ALL Code EDM Station Zero SetHA
 (2) Press [F3](SetHA) to enter the interface of SetHA. Screen displays the current value of HA. A: If want the current value of HA as the orientation angle, press [F4](OK) or press [ESC] to go back. 	[F3] [F4]	[SetHA] HA : 359° 39′ 01″ Zero 0K A: [OK] [SetHA]
B If want other value of angle as the orientation angle, you		HA : <u>359° 39′ 01″</u> Zero OK B: Input angle



3.3.2 Set Station and instrument height

After set the coordinate of station (the site of instrument) relatives to the

origin, the instrument can calculate the coordinate of the location to your position (the site of prism).

You can set station and the instrument height conveniently in the Q-Survey.

Steps	Key	Display		
(1) Aim at the target which used to orient. Press [F4] twice to enter third pages soft key.	[F4] + [F4] + [F2]	[Q-Survey] 1/3 Pt. : A1 . T. H. : Code : HA : YA : YA : ALL DIST REC ↓ ALL Code EDM ↓ Station Zero SetHA ↓		
 2) Press [F1] (Station) to enter the interface of Enter STA. Enter the name of station, the instrument height and coordinates. After entering each item, move the cursor to the next edit text. 	[F1]	[Input STA] Station : DEFAULT T. H. : 1.000 m XO/NO : 0.000 m YO/EO : 0.000 m ZO/HO : 0.000 m OK		

of Q-Survey.	A1 1.500m 00'00" 59'23" REC
--------------	---

3.3.3 Measurement

After all settings have been finished, you can start to measure. There are 3 pages to display the result of measurement, including all measurement data and you can press [PAGE] to view.

Steps	Key	Display		
(1) Input the name of point and instrument height. Move the cursor to the next edit text after entering each item. You can enter Code when necessary.	[ENT] + [ENT]	[Q-Survey] 1/3 Pt. T. H. Code HA 0° 00' 00" VA All DIST ALL DIST		

(2) Aim at the center of prism, press [F1](ALL) or [F2](DIST)+[F3](REC) to start to measure and record the measurement data. The measurement data including angle data, distance data and coordinate data. You can press [PAGE] to view.	[F1] or [F2] + [F3]	[Q-Survey] 1/3 Pt. : A1 T. H. : 1.500m Code : HA : 0° 00′ 00″ VA : 90° 59′ 23″ ↓ 10.044m ALL DIST REC ↓
3 After finishing measuring a point, program makes the number of point add 1 automatically, aim at the center of prism and repeat the above steps to start next point measurement.		[Q-Survey] 1/3 Pt. . T. H. . Code . HA . 0° 00' VA . 90° 59' 10.044m ALL DIST

3.3.4 Code

The code contains the information about the recording points, in the process of post-processing, with the help of encoding function, you can process conveniently according to the specific group. The function of "File Manager" also contains the information of code.

Simple Operation of Code

- 1. Move the cursor to the line of Code.
- 2. Enter the name of Code.
- 3. Press the key of [ALL] to start the distance measurement and record the data of code and measurement at the same time. If the name of code already exists in the code library, it will extract the information of code in the code library to record at the same time.

Steps	Key	Display
(1) Move the cursor to the line of Code.	↓	[Q-Survey] 1/3 Pt. T. H. 1.500m Code HA YA 90° 59' ALL DIST
(2) Enter code and press [ENT] to make sure. The entered code here will not be added to the code library.	Input code + [ENT]	[Q-Survey] 1/3 Pt. : T. H. : 1. 500m Code : HA : 0° 00' VA : 90° 59' ALL DIST

 ③ Press [F1] to start to measure, record the code and the date of measurement to job at the same time. ※¹ 	[Q-Survey] 1/3 Pt. : A3 T. H. : Code : HA : 0° 00' VA : 90° 59' A3 A3 T. H. 1. 500m Code HA 0° 00' VA : ALL DIST REC ↓
---	--

 \times^1 : The order to save code and measurement data is set in the "Setting" function.

The set items of code record are Before REC and After REC.

Before REC: Record code data before recording the actual measurement data.

After REC: Record code data following after the actual measurement data.

Soft key of Code

After starting the function of soft key (Code), Screen displays the following:

[View Co	ode] 1	/5	$\overline{\mathbf{v}}$
Code	:	COD	EA♠
Note	:		
Info 1	:	AAA	AAA
Info 2	:	BBE	BBBB
Info 3			
Info 4	:	DDE	DDDD
Find	New	REC	OK

GSI-the introduction of code properties:

Code: The name of code

Note: The additional note

Info1: The editable information of other contents Info8: Other information

The introduction of soft key:

[Find]: Use the name of code or wildcard to find the needed code.

[New]: New a piece of editable information of code and use it.

[REC]: Record the current code data to the job and the code data not with any measurement point binding at this time.

[OK]: Select the current code and use it.

Using the soft key of [Code] can select the code in the code library directly, it will back to the interface of Q-survey after selecting, the code in the edit text of Code is the selected code.

4 Functions

Bring the total station's common functions and settings together, they can be used in the process of measurement conveniently. In the function of Q-Survey which in the Main menu or other interface of measurement in the program, you can press [FNC] to enter the menu of Function


The menu of Function has 4 pages, you can press **[**PAGE**]** to view. The specific introduction as follows:

[Function]	1/3	•	[Functio	n]	2/3	\$
F1 Level		(1)	F1 Hidd	en poin	t	(5)
F2 Offset		(2)	F2 Free	Coding		(6)
F3 NP/P		(3)	F3 Lase	r		(7)
F4 HT. Transfe	er	(4)	F4 Ligh	t		(8)
F1 F2	F3	F4	F1	F2	F3	F4
	[Function	on]	3/3	•		
	F1 Unit	. Settir	ıg	(9)		
	F2 <mark>M</mark> air	n Settir	ıg	(01)		
	F3 EDM	Trackin	ıg	(02)		
	9					
	F1	F2	F3			

You can open Function menu to select the function you want to use, you can also define the function which on the Function menu to the key of [USER1] or [USER2], then press the key of [USER1] or [USER2] to use these functions.

4.1 Level

When the compensator is on, Compensator can compensate to the tilt caused by the instrument is not level. Manually level the instrument with the tribrach screws to make the compensation value of compensator tend to 0, by doing these can make the instrument tend to level. When the instrument is level, the laser plummet is in the direction vertical, the place of laser points is the place of instrument station.



◆ Press [On] to open the compensator and press [Off] to close the compensator.

• Press [X Only] to open the compensator of X direction.

• Press $[\blacktriangle][\triangledown]$ to adjust the laser plummet brightness.


• Press [OK] to close the laser plummet and exit.

4.2 Offset

The Offset is used to measure the points which are not intervisible, or intervisibility but can not set up prism in the Station.

Offset contains Dist. Offset and two subprograms, the two subprograms are Cylinder Offset and Angle Offset.

4.2.1 Distance Offset



Using the external tools to measure the Offset values of the target point p2 and measurement point p1 along the line of station point and measurement point, the Offset values are Trav.OFS, LengthOFS and HeighOFS. Combining the information of measuring point (p1) can calculate the distance of station point (p0) to target point (p2), can also calculate the angel and coordinate.

When the measurement point is set on the left of target point or the right of target point, you should make the angle that between line of measurement point and target point and the line of measurement and station point about equals 90° . When the offset point is set on the front of target point or on the back of target point, you should make it on the line of station point and target point.

Steps	Key	Display


(1) In the program of Q-Survey, press [FNC] to open the menu of Function, next pressing [F2] to enter the program of Offset.	[F2]	[Function] 1/3 F1 Level (1) F2 Offset (2) F3 NP/P (3) F4 HT. Transfer (4) F1 F2 F3 F4
(2) Input the values of Trav.OFS, LengthOFS and HeightOFS, then select the mode of offset and press [F4] to save. \times^{1}	[F4]	[Dist. Offset]Input offset data!Trav. OFS :0.000 mLengthOFS:0.000 mHeightOFS:0.000 mMode:ResetCylinderAngleOK

 \mathbb{X}^1 :

Rec/Reset: Make sure the inputed values of Offset and reset all the values of Offset to 0 after once measurement.

Permanent: The values of Offset are always working in the calculation of measurement point.


4.2.2 Cylinder Offset




As for the not intervisible cylinders, you can measure the angles of station point with cylinder in Hz Left and Hz Right and the shortest distance of station point to cylinder firstly. Then calculate the coordinate of cylinder center and radius of cylinder through the geometric relationships. The shortest distance between station point and cylinder is in the bisector of angle of station point with cylinder in Hz Left and Hz Right. Turning the instrument to make the collimation axis in the bisector of angle that station point with cylinder in Hz Left and Hz Right, thus can measure the distance between cylinder and station.

Steps	Key	Display	
(1) In the program of Q-Survey, press [FNC] to enter the menu of Function, then pressing [F2] to enter the program of Offset.	[F2]	F1 Level (F2 Offset (F3 NP/P (F4 HT. Transfer ((1) (2) (3) (4) F4

(2) Press [F2] to enter the subprogram of Cylinder Offset.	[F2]	[Dist. Offset]Input offset data!Trav. OFS :0.000 mLengthOFS:0.000 mHeightOFS:0.000 mMode:ResetCylinderAngle0K
(3) Aim at the left edge of cylinder, press [F1] to make sure the angel of Hz Left, turn the instrument to aim at the right edge of cylinder and press [F2] to make sure the angle of Hz Right.	[F1]+[F2]	Cylinder Offset] Hz Left : 125° 36′ 25″ Hz Right : 88° 45′ 46″ Image: Straight in the stra
(4) Turn the instrument to make \triangle Hz=0, if use the prism, please input the thickness of prism in the edit text of PrismOFS, if don't use the prism, the	[F3] or [F4] + [F1]+[F2]	[Cylinder Offset] Hz Left : 125° 36′ 25″ Hz Right : 88° 45′ 46″ Image: Straight : 0.000 m Image: Amount in the straight i



4.2.3 Angel Offset




Angle Offset is used to measure the points which are intervisible but have -50-

no reflector and can't set up the prism. The basic principle is making the target point and measurement point in the concentric circles whose center is station point, then measurement the position information of station point and measurement point and the angle offset of station to target point, thus can calculate the coordinate of target point.

Set the measurement point P in the place where is as far as possible to close the left or right of target point C, and make the distance between measurement point P and station point A and the distance between station point A and target point C are approximately equal.

Steps	Ke y	Display
(1)IntheprogramofQ-Survey,press[FNC]toenterthemenuofFunction,thenpressing[F2]to	y [F 2]	Function 1/3 - F1 Level (1) F2 Offset (2) F3 NP/P (3) F4 HT. Transfer (4) F1 F2 F3 F4
enter the		


program of Offset.		S
 2 Press [F3] to enter the subprogra m of Angel Offset. 	[F 3]	[Dist. Offset] Input offset data! Trav.OFS : 2.000 m LengthOFS: 1.000 m HeightOFS: 0.000 m Mode : Rec/Reset↓ Reset Cylinder Angle OK
 (3) Aim at the measure ment point and press [F1] to measure distance. 	[F 1]	[Angle Offset] Pt. : 1 T. H. : 1.550m HA : 89° 51′ 16″ VA : 12° 35′ 45″ : 12.235m DIST OK



[Angle Pt.	:	•	1		
Note	:	1000			
HA	:	123°	36′32″ 35′45″		
∆Hz	:	12°	35′45″		
	:		12.235 m		
Done			New		
				_	

4.3 NP/P Toggle

Switch the mode of reflector quickly. (P is the mode of Prism and NP is the mode of Non-Prism)




Open the first page of Function Menu and press [F3] to switch the mode of reflector.

4.4 Height Transfer

The functions of HT. Transfer as follows: Using the measurement data of target point, the fixpoints, fix measurement points and so on to calculate the height of current station point and set the height of station again. You can receive the coordinate of target point by calling the points in the file or through the keyboard to input, you can observe 5 fixpoints' height at most and to calculate.

The principle of Height Transfer:



(1) Press [F4] or [4] in the first page of [Function] to enter the function of Height Transfer measurement.	[F4] or [4]	[Function] 1/3 F1 Level (1) F2 Offset (2) F3 NP/P (3) F4 HT. Transfer (4) F1 F2 F3 F4 Select target and meas.! 1 Select target and meas.! Select target and meas.! Pt. : 1.200m T T Z : m M M ALL DIST REC ↓
(2) Press [F4] twice and display the third page of soft keys, press [F2](IH)to enter the function of setting instrument height, inputting the current instrument height and press [F4] to back to the function of Height Transfer interface.	[F4] + [F4] + [F2] + [F4]	[Height transfer] 1 Select target and meas.! ↓ Pt. : T. H. : 1.200m Z : m ALL DIST REC Find List Coord. EDM TH. View [Height transfer] 1 Station : STN IH. : 1.300 m XO/NO : 100.000 m YO/NO : 100.000 m ZO/HO : 10.000 m

 ③ Select the fixpoint and input the height of Prism. The numbers of measured fixpoints are displayed in the top right corner. There are 3 methods to selecting fixpoint. A: Press [F4] to enter the second page of soft key and press [F2](List) .In the dialog of [Find Pt.], by pressing [▲] or [♥] to select the fixpoints to call. 	[F4] + [F2] + [F4]	[Height transfer] 1 Select target and meas.! Pt. Pt. : Pt.1 T.H. : 1.200m Z : 2.500m ALL DIST REC ALL DIST REC ALL DIST REC A: [List] 1/50 DEFAULT Station 200007 Meas. PT 200008 Meas. PT 100 Fix Pt. 101 Fix Pt. View Coord. Job
B: Input the name of point and press [F1] (View) to view the point whether exists in the file or not. If exists, you can call it, otherwise, you need to input or measure the coordinate of the point.	[F1] (View) + [F4] (OK)	B: Search point [Find Pt.] 1/3 1 Station 1 Meas. PT 1 Fix Pt. View Coord. Job OK
C: Press [F2] (Coord.)	[F3]	C: Input point


and input a point name which not exists in the file.	(Coord) + [F4]	[Input Coord.] Job : DEFAULT Pt. : DEFAULT N : O.000m E : O.000m Z : O.000m Back OK
(4) After finishing setting up the fixpoint, the height of fixpoint is displayed in the screen and press [F1](ALL)or [F2](DIST)+[F3](REC) to start to measure and calculate, the height of station is calculated.	[F1] or [F2] + [F3]	[Height transfer] 1 Select target and meas.! 1 Pt. : Pt.1 T.H. : 1.200m Z : 2.500m M : m ALL DIST REC

(5) In the interface of		[Height 1 Station	transf	er res.] 🖕 STN
[Height Transfer Result],		ZO/HO	:	0.781 m
pressing [PAGE] to		0		0000
switch the display of		Correc. PT NUM.	:	0.000 m 1
result information.		1 1 1000	•	1
Press [F1](Add PT) to		ADD PT		Back OK
add a new point and to	[PAGE]			
start a new measurement.		[Height	transf	
Press [F3](Back) to back		Station XO/NO		STN 0.081 m
to measure the current		Y0/E0	:	0.081 m
point again.		ZO/HO	:	0.081 m
Press [F4](OK)to enter		PT NUM. Errors	:0	0.000 m
the interface of [Set STA		ADD PT		Back OK
HO].			2//	Duck
6 Pressing [F1] to back				
to the interface of [Height		e	_	
Transfer Result].		[Set STA	HO]	
Press [F2] to set the		Station	•	STN
height of station to the old		01d H0	:	0.781 m
value		New HO	:	0.781 m
Press [F4] to set the		∆HO	:	0.781 m
height of station to the		Back	OLD	AVG NEW
new value which		Duon		
calculated after Height				
Transfer.				

Press [F3] to set the	
height of station to the	
average of the old value	
and new value	œ

4.5 Hidden Point

The function of Hidden Point is using a special hidden point measuring rod to measure the points which are not intervisible.



The length of measuring rod is known, by measuring the position information of prism 1 and prism 2 in the measuring rod and using mathematical methods to calculate the coordinate of hidden point on the other side of the measuring rod.

Steps	Key	Display	
(1) In the program of Q-Survey, press [FNC] to enter the menu of Function, then pressing [PAGE] to open the second page of Function and then pressing [F1] to	[F1]	[Function]2/3F1 Hidden pointF2 Free CodingF3 LaserF4 LightF1F2F3	 ◆ (5) (6) (7) (8) F4

enter the function of hidden point measurement.		Ċ
(2) In the interface of measuring the first prism point, pressing [F4] to enter the interface of Rod Length.	[F4]	[Hidden point] Meas. Target 1! Pt. : HA : 89° 51′ 16″ VA : 12° 35′ 45″ ∴ 12.235 m ALL DIST REC ROD/ED
(3) Inputting the correct value of Rod length and pressing [F4] to back to measure the first prism point.	[F4]	[Rod Length] Rod Length : 3.000 m R1-R2 : 1.000 m Error Limits: 0.001 m OK

(4) The instrument aims at the prism on the top and pressing [F1] to finish measuring the first prism and enter the interface of measuring the second prism.	[F1] or [F2] + [F3]	[Hidden point] Meas. Target 1! Pt. : HA : 89° 51′ 16″ VA : 12° 35′ 45″ ↓ ▲ : 12.235 m ALL DIST REC ROD/ED
(5) Aim at the second prism and press [F1] to finish the second prism's measurement. Start to calculate the information of hidden point now. If the error is beyond the set value, enter the step (6) of giving a prompt of error, otherwise, enter step (7) to display the result of hidden point measurement.	[F1] or [F2] + [F3]	Hidden point] Meas. Target 1! Pt. 2 HA 89° 51′ 16″ VA 12° 35′ 45″ Image: Structure 12.235 m ALL DIST REC ROD/ED


6 A prompt of error. Press [F1] to enter the step 7 to display the result of hidden point measurement, press [F4] to back to the step 2 .	[F1] or [F4]	[Hidden point] Overrange Error Limits: 0.050m Error : 0.065m Accept New
(7) Display the result of hidden point measurement.		[Hidden piont-result] Pt. 1 Note 1 N 4.325m E 4.365m Z 2.235m Done New

4.6 Free Coding

Please refer to "3. Q-Survey" \rightarrow "3. Start Measurement" \rightarrow "3.4 Code"

4.7 Laser Pointer

Open or close the laser fastly.



4.8 Light


Turn on or off the light of instrument screen fastly.

[Function]		2/3	÷
F1 Hidder	n point	t	(5)
F2 Free (Coding		(6)
F3 Laser	F3 Laser		
F4 Light			(8)
F1	F2	F3	F4

Open the second page of Function Menu and press [F4] to turn on or off the Light.

4.9 Unit Setting

Set the common Unit fastly.



Open the third page of Function Menu and press [F1] to enter the interface of unit setting. After finishing setting the units in the interface of Unit Setting, press [F4](OK) to save the settings, press [F1](Reset)to restore all units to factory default.

4.10 Main Setting


Open the settings about instrument's hardware, the spe cific items as follows:

[Function]	3/3 ^	1	Light :	High 🔶
F1 Unit Setting	(9)		Trigger Key :	DIST 🐠
F2 Main Setting	(01)		User Keyl	Level 🐠
		(F2)	User Key2	NP/P •
F3 EDM Tracking	(02)		Key Beep :	On 🏶
			Sector Beep :	0ff ♦
			Tilt :	0ff ♦
F1 F2	F3		Reset	OK

As for the setting of specific items, please refer to "General Setting".

4.11 EDM Tracking

Open or close the mode of EDM Tracking fastly.



Open the third page of Function Menu, press [F3] to open or close the mode of EDM tracking.

5 Applications

Prepare setting before measuring:

Before starting the application, there are some preparations needed to set up. The Pre-Settings screen will be shown after the user selects an application. User can select and set the content of the Pre-Settings menu successively.

[Survey:	ing]	
[*] F1	Set Job	(1)
[*] F2	Set STA	(2)
[] F3	Set B.S.	(3)
F4	Start	(4)
F1	F2 F3	F4
n done.		
been done.		
setting are	e as follows.	

[*]: Setting has been done.

[]: Setting has not been done.

The details of every setting are as follows.


5.1 Setting the Job

The measured data and fix data are saved in the jobs which are shown as child directories. The job contains different types of data, such as fix points, measured points, station points, codes, etc. The data in the job can be read, edited and deleted.

5.1.1 Create a new Job

Steps Key	Display
-----------	---------

(1) Press [F1] in the Pre-Settings screen. Then enter the Set Job function.	[F1]	[Surveying] [*] F1 Set Job (1) [*] F2 Set STA (2) [] F3 Set B.S. (3) F4 Start (4) F1 F2 F3 F4
 2 Press [F2](New) and then enter the Create a New Job screen. Press [F4](OK), the displayed job will be set as current job and then back to Pre-Settings screen. 	[F1]	[Set Job]Job:DEFAULTOperator :
(3) Continue to show New Job screen. Input the new job's name, operator, etc. Press [ENT] to finish one input item and the cursor moves to the next input item automatically at the same time. \times^1	Input job's data + [ENT]	[New Job] Job : Job : Operator : Note1 : Note2 : Date : 2015.05.15 Time : 14:10:20 Back OK



5.1.2 Select an Existing Job from Memory

If there is any job existing in the memory, user can select this job and set it as the current job.

Steps	Key	Display
(1) Press [F1] in the Pre-Settings screen. Then enter the Set Job function.	[F1]	[Surveying] [*] F1 Set Job (1) [*] F2 Set STA (2) [] F3 Set B. S. (3) F4 Start (4) F1 F2 F3 F4


(2) Press [F1] (List) to enter Job list screen.	[F1]	[Set Job]Job:DEFAULTOperator ::Date:2015.05.15Time:14:10:20ListNewOK
(3) All the existing jobs, including that stored on SD Card and will be shown as a list. The current job is marked with a *. Select the target job through Up and Down key and then press [F4](OK) to confirm the selection. The selected job is set as current job.		[Job list] JOB1 JOB2 JOB3 JOB4 JOB5 JOB6 Delete New View OK
(5) Back to Pre-Setting screen. The completed setting item is marked with *.	[F4]	[Surveying] [*] F1 Set Job (1) [*] F2 Set STA (2) [] F3 Set B.S. (3) F4 Start (4) F1 F2 F3 F4

Note: Don't pull out the SD Card when it is in operating state, otherwise it will cause the SD Card's data loss or damage.

- > All measured data are stored in the current job.
- If start the application without setting the job, press ALL key or press REC key in the Q-Surveying screen, the instrument system will create a job which named DEFAULT automatically.

5.2 Setting the Station

Every target coordinate's calculation is related to the position of the station. The station coordinate can be input manually or selected from the instrument memory.



5.2.1 Select the coordinate from memory [Find]


Steps:

- 1. Select the coordinate from memory.
- 2. Input instrument height.
- 3、 [OK] Set station.

Steps	Key	Display
(1) Press [F2] in the Pre-Settings screen. Then enter the Set STA function.	[F2]	[Surveying] [*] F1 Set Job (1) [*] F2 Set STA (2) [] F3 Set B.S. (3) F4 Start (4) F1 F2 F3 F4
(2) Input the name of the station point which exists in the job and then press [ENT]. ^{*1}	Input point name + [ENT]	[Set STA] Input STA PT! Station : DEFAULT Find List Coord.
(3) Press [F1](Find): A: If the input name exists in the current job, there will show the screens shown on the right figure. The multiple points with the same name will be sorted by type.		A: [Find Pt.] 1/5 1 Station A1 Station A1 Meas. PT A1 Meas. PT A1 Target PT View Coord. Job OK B:

B: If the input name		[Find Pt.]
doesn't exist in the	1	Job : DEFAULT
current job, the	l	Pt. : <u>121</u>
program prompts the	l	\odot
message "Pt. not	l	Select job or input coord.!
found". Then enter the	l	
[Find Pt.] screen.	l	Job Zero Coord. Find
There can also select	l	[Set STA]
point from other jobs	1	Job : DEFAULT
and set it as the station	1	Pt. : 121
point. Input the point	l	N : 0.000m
name and press		E : 0.000m Z : 0.000m
[F4](Find). If the point		
is found, press [OK] in		Back OK
the [Find Pt.] list		15
screen to set it as		\sim
station. Program enter		
input instrument		
height screen. If the		
point doesn't exist,		
press [F3](Coord.) to		
input the coordinates	1	
of N, E and Z. Set this	l	
point as station.	l	
[Zero]: Set this	1	
point's all coordinates	1	

as 0 and set the point as station. [Coord.]: Enter [Input Coord.] screen. Input the coordinates and save them to the current job.		Ċ
(4) Enter input instrument height screen. Input the instrument height and press [ENT] to confirm. Then press [F4](OK) to save and set the station information. Press [ESC] then back to previous screen. Continue to set the coordinates of station.	Input instrument height + [ENT] + [F4]	[Set STA] Input I.H! IH. : 0.000m Back OK



5.2.2 Select the Fix Point in the Memory [List]

User can select the fix point in the memory's jobs to set station without inputting the point name.

Steps	Key	Display
(2) Press [F2](List) in the [Set STA] screen.	[F2]	[Set STA] Input STA PT! Station : A1 Find List Coord.

(3) Show the point list all the fix points and measured points of the current job.	[Find Pt.] DEFAULT STN1 200007 200008 100 101 View Coor	1/50StationStationMeas. PTMeas. PTFix Pt.Fix Pt.Fix Pt.d. JobOK
 (4) Select the needed point through Up and Down key. [View]: Show the information of this point. [Coord.]: Input the coordinate data manually. [Job]: Select data from another job. 	[View]: [View Coord] Job : Pt. : N : E : Z : Date : Date : [Coord.]: [Coord.]: [Set STA] Job : Pt. : N : E : Z : Back [Job]:	DEFAULT A1 0.000m 0.000m 2015.05.15 OK DEFAULT 121 0.000m 0.000m 0.000m

Et job or input coord. ! Zero Coord. Find
TTA] Input I.H! : 1.400m OK


5.2.3 Input the coordinates manually.

Steps:

- 1. Press [Coord.], enter input coordinate screen.
- 2. Input the point name and coordinates.
- 3. [OK] Save the station coordinates. And then input the instrument height.

Steps Key	Display
-----------	---------

(2) Press [F3](Coord.) in the [Set STA] screen.	[F3]	[Set STA] Input STA PT! Station : A1 Find List Coord.
(3) Input the point name and the point's coordinates. After inputting one item, the curser will move to next input item.	Input point name and coordinate + [ENT]	[Input Coord.] Job : DEFAULT Pt. : 121 N : 3.012m E : 15.012m Z : 4.125 Back OK
(4) Press [F4](OK) to save the coordinates of this point.	[F4]	[Input Coord.] Job DEFAULT Pt. 121 N 3.012m E 15.012m Z 4.125m Back OK



5.3 Setting the Orientation

The orientation can be input manually or determined from points that are either measured or selected from the memory.

5.3.1 Manual input orientation


Steps 1. Press [F1] and enter manual input screen.

2. Input the azimuth, prism height and point name.

3.Press [F1](ALL) to start measuring and set the orientation.

4.Press [REC] to record the angle and orientation.

Steps	Key	Display
(1) Press [F3] in the Pre-Settings screen. Then enter the Set STA function.	[F3]	[Surveying] [*] F1 Set Job (1) [*] F2 Set STA (2) [] F3 Set B.S. (3) F4 Start (4) F1 F2 F3 F4
(2) Press [F1] and select the [Angle Setting] to input orientation manually.	[F1]	[Set B.S.] F1 Angle Setting (1) F2 Coordinates (2) F1 F2
(3) Aim B.S. point and then input the azimuth, prism height and backsight point name. Press [ENT] after finishing every input.	Input horizontal angle + [ENT]	[Angle setting]Azimuth :50° 00′ 00″T.H. :1.500 mBS PT :DEFAULT1Aim BS. Then ALL/RECALLRECZeroEDM




5.3.2 Set orientation with coordinates


The determination of the direction value can also be carried out using a point with a known coordinate.

Steps:


- 1. Press [F2] to go to set orientation with coordinates
- 2. Input the name of orientation point and find the point.
- 3. Input the prism height and determine it.
- 4. Use this point to set orientation.




> The orientation point can be select from memory or inputted manually.



EC) to	Meas. BS
start	BS PT : DEFAULT1
measur	T. H. : 1. 500 m HA : 45° 00′ 00″
ing and	Ţ S
finish	△ : 10.000 m 🕅
setting	$\triangle Z$: 1.726 m
orienta	ALL DIST REC EDM
tion.	
User	
can	
also	
press	
[F3](R	
EC) to	
finish	
setting	
orienta	
tion	
withou	
t	
measur	
ement.	
Press	





5.4 Starting the Applications

The preset applications covers a wide range of measurement tasks. That makes the daily field measurement easier and faster. The all applications can be selected to use are as follows:

- Surveying
- Stakeout
- Free Station


- Tie Distance
- Area
- Remote Height
- COGO
- Road

Steps:

- 1. Go to the MAIN MENU.
- 2. Move the focus to [Program] or press the Numeric key 2 to select and go to the PROGRAM MENU.
- 3. Press [PAGE] to browse the application menu. Press [F1]-[F4] to select and start an application.

5.5 Surveying

Compared with the Q-Surveying, Surveying has different guides in setting station and set orientation.



Operation: Must first finish setting the station and orientation.

Steps	Key	Display
(1) After finishing setting the job, setting the station and setting the orientation, press [F4] to start the application in the Pre-Setting menu.	[F4]	[Surveying] [*] F1 Set Job (1) [*] F2 Set STA (2) [] F3 Set B.S. (3) F4 Start (4) F1 F2 F3 F4
 2 Input the point name, and then press [ENT] to move to next input item to input prism height. 	Input point name + [ENT]	[Surveying] 1/3 Pt. : T. H. : Code : HA : 13° 29' 59" VA : 90° 59' 23" ALL DIST REC
(3) Input the prism height and then press [ENT] to move the cursor to next input item. If needed, input the code.	Input prism height + [ENT]	[Surveying] 1/3 Pt. 1 T. H. 1.500m Code 1 HA 13° 29' 59" VA 90° 59' 23" ALL DIST

(4) Press [F1](ALL) or press [F2](DIST) and [F3](REC) to start measuring and record the measured data. This data contains angle, distance and coordinates. Press [PAGE] to switch the display mode of the data.	[F1] or [F2]+[F3]	Surveying] 1/3 Pt. 1 T. H. 1.500m Code 1 HA 13° 29' 59" WA 90° 59' 23" Image: Contract of the second se
(5) After finishing measuring one point, the point name automatic plus one. Press [F1](ALL) or press [F2](DIST) and [F3](REC) to continue measuring next point. At this time, the screen remains the last measured data which can be looked over by pressing [PAGE].		Surveying] 1/3 Pt. 2 T. H. 1. 500m Code 13° 29' 59" HA 13° 29' 59" VA 90° 59' 23" I. 10. 044m ALL DIST

5.5.1 Individual Point

[IndivPt]:

In the data acquisition, point can be recorded individually. Press this key to switch the screens of Individual Point Measurement and Consecutive Point Measurement.


Steps	Key	Display
 Press [F4](↓) twice to display the last page of soft keys. 	[F4]	Surveying 1/3 Pt. 1 T. H. 1.500 m Code 1 HA 13° 29' 59" VA 90° 59' 23" ALL DIST ALL Code ALL Code ALL IndivPt Data ←
(2) Press [F2](IndivPt) to start measuring individual point function.	[F2]	[Surveying] 1/3 IndivPt 2 T. H. 1.500 m Code 1 HA 13° 29' 59" VA 90° 59' 23" ALL IndivPt Data ←


(3) Input the individual point's name and prism height and press [ENT] to move the cursor to next input item If needed, input the code.	Input point name, prism height and code + [ENT]	[Surveying] 1/3 IndivPt : T. H. : T. H. : Code : HA : 13° 29' VA : YA : ALL IndivPt Data
(4) Press [F1](ALL) or press [F2](DIST) and [F3](REC) to start measuring and record the measured data.	[F1] or [F2]+[F3]	[Surveying] 1/3 IndivPt : T. H. : 1.500 m Code : Image: Second se
(5) Finish measuring, application turn off the function of measuring individual point and then continue to display the consecutive point name.		[Surveying] 1/3 IndivPt 2 T. H. 1.500 m Code 1.500 m HA 13° 29' 59" VA 90° 59' 23" ALL IndivPt Data ←

5.5.2 Data

[Data]:


Look over the measured data which are saved in current job.






[
S	
[EN	
T]	
and	
then	
pres	
S	
[F4]	
(Vie	
w)	
to	
look	
over	
the	
data.	
If	
ther	
e is	
no	
matc	
h	
poin	
t,	
the	
prog	
ram	

pro mpts "Pt. not foun d!" [Job	©
]:	
Sele	
ct	
the	
job	
whe	
re	
the	
mea	
sure	
d data	
is to	
be	
view	
ed.	



field	[Vie	ew Meas Pt]	1/28 🜲	
of	EDM	Mode :	Non-Prism	
this	P. C.		0. Omm	
poin				\odot
t.				
Pres				
s	De1	ete	Search	
dire				
ctio				
n				
key				
←				
and				
\rightarrow				
to				
bro				
wse				
the				
last				
or				
next				
mea				
sure				
d				
poin				
t.				



5.6 Stakeout

The Stakeout Application can calculate lofting elements base on lofting point's coordinate or manually input angle or horizontal distance. The $_{-98}$ -

application can continuously display differences, between current position and desired stake out position.

Steps of Stakeout :

- 1. Set the job.
- 2. Set the station
- 3. Set the orientation
- 4. Extract coordinates from memory. The coordinates may be a measured point or a manually entered fix point.
- 5. Start staking out. There are three ways to choose: Polar Stakeout mode, Orthogonal to Station Stakeout mode, Cartesian Stakeout mode.


5.6.1 Set Stakeout Point

• Extract coordinates from job

Steps	Key	Display
 After finishing setting the job, setting the station and setting the orientation, press [F4] to start staking out in the Pre-Setting menu. 	[F4]	[Stakeout] [*] F1 Set Job (1) [*] F2 Set STA (2) [*] F3 Set B.S. (3) F4 Start (4) F1 F2 F3 F4

(2) Input the name of stakeout point in the Search item. Press [ENT] to start Find Point function. (Or input wildcard "*"to start the wildcard search.)	Input stakeout point's name + [ENT]	[Stakeout] 1/3 Search : * Pt. 5 ◆ T. H 1.500m △Hz △▲ ▲▲ ▲▲ ▲▲ ▲▲ ▲▲ ▲▲ ▲▲ ▲▲ ▲▲ ▲▲ ▲▲ ▲▲ ▲▲ ▲▲
(3) A: The program search the point name in the job and show the result dialog. The match points will be listed, press [F4](OK) to identify selected point		[Find Pt.]1/205Fix PTB1Meas. PTB2Meas. PTB3Meas. PTB4Meas. PTViewCoord.JobOK
and back to Stakeout screen. (If the input is wildcard "*", the program will show all the points of the current job.) ² B: If there is no match		[Find Pt.] Job : DEFAULT Pt. : A12 Select job or input coord.! Job Zero Coord. Find

- 100 -



 **¹: The settings of job, station and orientation have been elaborated in detail in the previous chapters, here is no longer repeat. Refer to chapters "Setting The Job, Setting The Station, Setting The Orientation".

*2: Unlike the other place's points list, the stakeout points are ordered by time. In the stakeout points list, the newest point is at the back and the fix point is in the front of measured point. But in the other points list, the newest point is at the back and the measured point is in the front of fix point.

• Manual input stakeout point

Press key [Coord.] or [SO-PT] to manual input stakeout point coordinates and then continue staking out.

[Coord.]:

Press [Coord.] and then input a target point's coordinates. Saved this point into job and continue staking out.

Steps	Key	Display
(1) Press [F4] (↓) to view the second page of soft keys.	[F4]	[Stakeout] 1/3 Search : * Pt. : T. H : △Hz : → : → -0.108m △ : ALL DIST EDM Coord. View + Polar SO-PT
(2) Press [F2](Coord.) to go to Input Coord. Screen. Input point name and coordinate of the stakeout point. After input one item, the curser will move to next input item.	[F2] + Input point name and coordinates + [ENT]	[Input Coord.] Job DEFAULT Pt. 5 N 0.000m E 0.000m Z 0.000m Back 0K

[SO-PT]:


Press [SO-PT] to input a stakeout point without point name and being saved into job.

Steps	Key	Display
(1) Press [F4] (↓) to view the third page of soft keys.	[F4]	[Stakeout] 1/3 Search : * Pt. : 5 ↔ T. H : 5 ↔ AHz : 1.500m △Hz : -0.108m △ : 1.008m A : 1.008m A : 1.008m B -0.175m ALL DIST REC EDM Coord. View Polar SO-PT Image: Constant of the second of t

(2) Press [F2](SO-PT) to go to SO-Input data screen. Input the coordinates of stakeout point. After input one item, the curser will move to next input item.	[F2] + Input point name and coordinate s + [ENT]	[SO-Input data] N : 0.000 m E : 0.000 m Z : 0.000 m Zero 0K
(3) After finishing inputs, press [F4](OK) to save the data. And then back to Stakeout screen. Start to stakeout the input point. The program will name this point DEFAULT automatically. ¹ ¹ : [SO-PT]: The input p		[Stakeout] 1/3 Search : 5 Pt. DEFAULT ◆ T. H 1.500m △Hz ← 13° 29' △ ↑ −0.108m △ ↑ ALL DIST REC ↓

 \mathbb{X}^1 : [SO-PT]: The input point won't be saved into job.

5.6.2 Polar Stakeout Mode



The meanings of the differences in the Polar Stakeout mode:

 \triangle Hz Difference in direction: If the measured point is located in the right side of stakeout point, the value is positive.

 \triangle Difference in horizontal distance: If the measured point is farther than stakeout point, the value is positive.





Difference in height: If the measured point is higher than

stakeout point, the value is positive.

Steps	Key	Display
(1) Set all the points that are readied to stake out. Select one stakeout point through search the point name in the job.		[Stakeout] 1/3 Search : Pt. : T. H : △Hz △ : ALL DIST
(2) Press [PAGE] to go to page 1/3(Default page). Press direction key and move the cursor to input prism height item. Input the prism height and then press [ENT] to confirm.	[PAGE] + ↓ + Input prism height + [ENT]	[Stakeout] 1/3 Search : 5 Pt. : 5 ↔ T. H : 2.000m △Hz : ← 13° 29' 59" > △ :
(3) Aim at the prism. Press [F2](DIST) to start measuring and calculate the differences between measured point and stakeout point.	[F2]	[Stakeout] 1/3 Search : 5 Pt. : 5 ◆ T. H : 1.500m △Hz : ← 13° 29' 59" △ ↑ -0.108m △ ↑ ALL DIST


 ④ Turn the instrument telescope to make the △ Hz equal 0° 00′ 00″ and command the staff to move the prism at the same time. Arrows Meaning: ←: Look forward from station and move the prism to the left. →: Look forward from station and move the prism to the right. 		[Stakeout] 1/3 Search : 5 Pt. 5 ◆ T. H 1.500m △Hz * 0° 00' 00" △ ↑ -0.108m △ ↑ ALL DIST
(5) While the \triangle Hz equals 0° 00′ 00″, press [F2](DIST) to start measuring and calculate the differences between measured point and stakeout point. The arrow's direction is the direction of the prism need to move.	[F2]	[Stakeout] 1/3 Search : 5 Pt. : 5 T. H : 2.000m △Hz : * 0° 00' 00" △▲ : ↑ -0.324m △▲ : ↑ -0.309m ALL DIST REC





5.6.3 Orthogonal to Station Stakeout Mode

Use longitudinal difference and perpendicular difference to indicate the position differences of stakeout point and current prism position.




The meanings of the differences in the Orthogonal to Station Stakeout Mode:

 \triangle Length Difference in longitudinal distance: If the measured point is farther than stakeout point, the value is positive.

 \triangle Trav. Difference in perpendicular distance: If the measured point is located in the right side of stakeout point, the value is positive.

Steps	Key	Display
(1) Press [PAGE] to show Orthogonal to Station Stakeout Mode in page 2/3. Set the stakeout point. The stakeout point can be	[PAGE]	[Stakeout] 2/3 Search : * Pt. : 6 ↓ T.H 1.500m △Length: △Trav. : △Z/H : ALL DIST REC ↓

found in the job through		
inputting point name in		
the search item.		
(2) Press direction key and move the cursor to input prism height item. Input the prism height and then press [ENT] to confirm.	 ↓ + Input prism height + [ENT] 	[Stakeout] 2/3 Search : * Pt. : 6 ↔ T. H : 1.800m △Length: △Trav. : △Z/H : ALL DIST
(3) Aim at the prism. Press [F2](DIST) to start measuring and calculate the differences between measured point and stakeout point. The arrow's direction is the direction of the prism need to move.	[F2]	[Stakeout] 2/3 ↓ Search : * * Pt. : 6 ◆ * T.H : 1.800m T △Length: 1.764m * △Trav. : 5.052m * △Z/H : 1.320m * ALL DIST REC




(5) Turn the instrument		
telescope to find the		
direction where makes		(C)
the \triangle Trav. equal 0m		[Stakeout] 2/3 🗘
and command the staff		Search : * 🛄
to move the prism at the		Pt. : 6 ↔ 🕅
same time.		T.H : 1.800m ∆Length: * 0.000m
Arrows Meaning:		∆Trav. : * 0.000m
←: Look forward from		△Z/H : ↑ -1.320m
station and move the		ALL DIST REC 🗸
prism to the left.		
\rightarrow : Look forward from		
station and move the		
prism to the right.		
(6) It means the current		\sim
prism position is		
effective stakeout point		[Stakeout] 2/3 ♀
while both the△Length		Search : * □ Pt. : 6 ↔ 🎽
and \triangle Trav. are 0.		T. H : 1. 800m
\triangle Z/H: Display as dig		△Length: * 0.000m
or fill data.		△Trav. : * 0.000m △Z/H : ↑ -0.780m
\downarrow : The value expresses		ALL DIST REC L
the depth of needed to		
dig.		
↑ : The value expresses		
† : The value expresses	- 12	13 -

the height of needed to fill.	
(8) Now it finishes staking out a point. Repeat the previous steps to stake out next point.	[Stakeout] 2/3 Search : * Pt. : 6 ◆ T. H : 1.800m △Length: △Trav. : △Z/H : ALL DIST REC ↓

5.6.4 Cartesian Stakeout Mode

Stake out point based on the Cartesian coordinate system. The deviation values are the coordinate differences.



The meanings of the differences in the Cartesian Stakeout Mode:


 \triangle Y/E The difference in East coordinate between measured point and stakeout point.

 $\triangle X/N$ The difference in North coordinate between measured point and stakeout point.

Steps	Key	Display
(1) Press [PAGE] to show Cartesian Stakeout Mode in page 3/3. Set the stakeout point. The stakeout point can be found in the job through inputting point name in the search item.	[PAGE]	[Stakeout] 3/3 Search : * Pt. : 5 ↔ T. H 1.500m T ∆Y/E X/N ∆X/N X ∆Z/H X ALL DIST REC ↓
(2) Press direction key and move the cursor to input prism height item. Input the prism height and then press [ENT] to confirm.	↓ + Input prism height + [ENT]	[Stakeout] 3/3 Search : * Pt. : 5 ♦ T. H : 2.000m △Y/E : T △X/N : * △Z/H : * ALL DIST REC ↓

(3) Aim at the prism. Press [F2](DIST) to start measuring and calculate the differences between measured point and stakeout point.	[F2]	[Stakeout] 3/3 Search : * Pt. : 5 ↔ T. H : 2.000m △Y/E : -0.306m △X/N : 0.504m △Z/H : -1.299m ALL DIST REC
(4) Move the prism along the East direction to make the value of \triangle Y/E equal 0m. \triangle Y/E is positive: The stakeout point is in the right side of measured point. Move the prism to right. \triangle Y/E is negative: The stakeout point is in the left side of measured point. Move the prism to left.		[Stakeout] 3/3 Search : * Pt. : 5 ↔ T. H : 2.000m ∆Y/E : 0.000m ∆X/N : 0.504m ∆Z/H : -1.299m ALL DIST REC

	Move the prism g the North tion to make the e of $\triangle X/N$ equal N is positive: The out point is farther the measured the measured the measured the process of ng out, if using the process of ng out, if using the the process of the process of ng out, if using the the process of the process of ng out, if using the the process of the process of	
--	---	--




5.6.5 Polar


Press [Polar], then input the polar stakeout elements: Azimuth and Horizontal distance. Start to stake out after finishing inputs of Azimuth and Horizontal distance.

Steps	Key	Display
 Press [F4](↓) twice to view the second page soft keys. 	[F4]	$Stakeout$ $1/3$ Search*Pt. $5 \leftrightarrow$ T. H1.500m Δ Hz \leftarrow 13° $29'$ Δ Δ ALLDISTREC \downarrow EDMCoord.View \downarrow PolarSO-PT
(2) Press [F1](Polar) to show the dialog as shown in figure.	[F1]	[Polar Stakeout] Pt. : Azimuth : OK
(3) Input the stakeout point's name, azimuth and horizontal distance. Press [ENT] to confirm every input and move the cursor to next input item. Press [F4](OK) to go to	Input point name, azimuth and horizontal distance + [ENT]	[Polar Stakeout] Pt. : <u>P001</u> Azimuth : 135° 33′ 23″ ▲ : 10.015m OK

- 119 -

D 1 0 1		
Polar Stakeout screen	+	
after finishing all	[F4]	
inputs. ^{%1}		
(4) Aim at the prism.		[Stakeout] 1/3 -
Press [F2](DIST) to		
start measuring and	[F2]	Pt. : P001
calculate the	[[2]	$\triangle Hz$: \leftarrow 39° 15′ 12″ $\textcircled{1}{8}$
differences between		△ : ↑ -6.132m
measured point and		New DIST REC Back
stakeout point.		New DISI REC Dack
(5) Turn the		
instrument telescope		
to make the \triangle Hz		
equal 0°00'00" and		[Stakeout] 1/3 -
command the staff to		[Stakeout] 1/3 🗸
move the prism at the		×.
same time.		Pt. : P001 🖗
		$\triangle Hz : \leftarrow 39^{\circ} 15' 12'' 32$
\triangle Hz is positive: The		△ : ↑ -6.132m
stakeout point is in the		
left side of measured		New DIST REC Back
point. Move the prism		
to left.		
\triangle Hz is negative: The		
stakeout point is in the		





 $\%^1$: The inputs of polar coordinate data won't be saved to job.

5.7 Resection


Resection measurement is an application used to determine the coordinate of the instrument station by measuring multiple known points. A minimum of 2 and a maximum of 5 known points can be used to determine the station. It should be used at least 2 known points by distance measurement or at least 3 known points by angle measurement.

Steps	Key	Display
(1) Select "Program" from the [Main Menu] window, press [F3] or number key [3] to enter the Resection application.	[F3]	[Program]1/3F1Surveying(1)F2Stakeout(2)F3Resection(3)F4Tie Distance(4)F1F2F3F4
2 Press [F1] in the [Resection] window to set the job.	[F1]	[Resection][*] F1 Set Job[] F2 Set Error LimitsF4 StartF1 F2 F4

(3) In [Set Job] window, press [F1] (List) to select a job in memory or press [F2] (New) to new a job. Then press [F4] (OK) to next step.	[F4]	[Set Job]Job:DEFAULTOperator :
(4) The window back to the [Resection] window, and press [F2] to set error limits.	[F2]	[Set Error Limits]Input error limits!StatusOffe(X/N)0.000me(Y/E)0.000me(Z/H)0.000mOK
(5) Press $[\blacktriangleleft] \setminus [\blacktriangleright]$ to turn on the error limits status and use the key $[\blacktriangle] \setminus [\blacktriangledown]$ to move the focus down to input the every error limit. Then press $[F4]$ (OK) to set and back to the [Resection] window.	Input error limits + [F4]	[Set Error Limits]Input error limits!Status :On e(X/N) :0.010me(Y/E) :0.010me(Z/H) :0.010mOK

6 Press [F4] in [Resection] window to start resection measurement. It should be input the station name and the instrument high. Then press [F4] (OK) go to next step.	[F4] Input name and IH. + [ENT] [F4]	[Resection-Station] Station : DEFAULT IH. : 1.000m OK
 ⑦ Set the first known point and input prism high₀ [※] ¹The title bar will display the number of known points in the current setting. 		[Resection-Target PT] 1 Pt. : 1 T.H. : 1.500m Find List 0K ↓
 (8) Turn the instrument telescope aimed at first point and press [F1] to finish current measurement. Angle measurement: press [F2] (REC) to record an angle. 	[F1]	[Resection-Observe] 1 Pt. : 1 T. H. : 1.500m HA : 177° 55′ 56″ HA : 177° 12″ VA : 89° 15′ 12″ ALL NEXT PT ↓

F	-	
Distance measurement:		
[F1] (ALL) or [F1] +		
[F2] (DIST + REC).		
 When finish a known point measurement, press [F2] (NEXT PT) to start next known point 	[F2]	[Resection-Target PT] 1 Pt. : 2 T.H. : 1.500m
measurement. Repeat steps (7) and (8).		FindListOK↓Coord.Back►
 If the measured known points are enough, [Result] will display on the screen, then press [F3] (Result) to enter the [Station Coordinate] to view station result. Press [F1] (Back) back to a new known point measurement. 		[Resection-Observe]2Pt. 2 T. H. $1.500n$ HA $177^{\circ} 55' 56''$ VA $89^{\circ} 15' 12''$ VA $89^{\circ} 15' 12''$ Ic. 132mALLNEXT PT ResultPress [F3] (Result) to enter the [Station Coordinate] to view result.
Press [F2] (errors) to		



5.8 Tie Distance


Tie Distance is an application used to compute slope distance, horizontal distance, height difference and azimuth of two target points which are either measured, selected from the memory, or input using the keypad.

The user can choose between two different methods:

- Polygonal: P1-P2, P2-P3, P3-P4
- Radial: P1-P2, P1-P3, P1-P4

Start Tie Distance application through "Main Menu" \rightarrow "Program" \rightarrow "Tie Distance".


5.8.1 Polygonal





While Polygonal tie distance measuring continuous points, the new tie distance's first point will use the previous one tie distance's second point(P1-P2, P2-P3, P3-P4.....).

Steps	Key	Display


(1) Press [F4] in the Program Menu to go to Tie Distance application.	[F4]	[Program]1/3F1Surveying(1)F2Stakeout(2)F3Resection(3)F4Tie Distance(4)F1F2F3F4
(2) After finishing setting job, station and orientation, press [F4] in the Pre-Setting menu to go to Select Tie Distance Mode screen.	[F4]	[Tie Distance] [*] F1 Set Job (1) [*] F2 Set STA (2) [*] F3 Set B.S. (3) F4 Start (4) F1 F2 F3 F4
(3) Press [F1] to select the Polygonal tie distance.	[F1]	[Tie Distance]F1PolylineF2RadialF1F2









5.8.2 Radial




While Radial tie distance measuring continuous points, the new tie distance's first point continues using the previous tie distance's first point(P1-P2、P1-P3、P1-P4.....).


Steps Ke y
 ① Press [F4] in the Program Menu to go to Tie







measure ment. ※ 1		NewPt2 3/3 ▲ PT1 1 PT2 2 T. H. 1.500m HA 125° 14′ 53″ VA 85° 35′ 42″ Image: State of the state
6		
Show the		
result of		
Radial tie		
distance.		
[NewPt1]		PT1 : 1
: Start a		PT2 : 2
new		Slope : 2.9%
Radial tie		△ : +1. 232m △ : -0. 562m
distance.		A → → → → → → → → → →
[NewPt2]		Azimuth : 12° 27′ 13″
: This		NewPt1 NewPt2 Radial
Radial tie		
distance'		
s first	1	
point		
continues		
to be the		



5.9 Area

Area is an application used to calculate the polygon areas to a maximum

of 20 points which connected by straights. The target points coordinate can be measured, selected from memory or entered via keypad in same direction. And the following three methods can be alternately performed. The calculate area is projected onto the horizontal plane (2D).




Figure 9.1 Area Diagram

P0 Instrument Point

P1 Start Target Point

P1~P5 Target Point

a Perimeter, polygonal length from start point to the current measure point.

S Calculated area always closed to the start point P1, projected onto the horizontal plane.

Select "Program" from the [Main Menu] window, then press [PAGE] switch to second program list and press [F1] or number key [5] to enter the Area application.

Steps	Key	Display
-------	-----	---------

(1) Select "Program" from the [Main Menu] window, then press [PAGE] switch to second program list and press [F1] or number key [5] to enter the Area app.	[PAGE] + [F1] or [5]	[Program] 2/3 F1 Area F2 Remote Height F3 COGO F4 Road F1 F2 F3	 \$ (5) (6) (7) (8) F4
(2) After finishing the pre-settings (know more details at the beginning of chapter 5), press [F4] to start Area app.	[F4] or [4]	[Area] [*] F1 Set Job [*] F2 Set STA [*] F3 Set B.S. F4 Start F1 F2 F3	(1) (2) (3) (4) F4


current point

 ④ On Area interface Press the key of F3 to select Result function. To display the 2D result(area, perimeter) 	F3	[AreaResult] PT Count : 3 Area : 12.362 m2 Area : 0.001 ha Area : 3.328 f2 Perimeter: 15.654m New Area Graph Add PT
--	----	---

%In all of the above operation, press [ESC] to return to the previous screen.

5.10 Remote Height

Remote Height is an application used to measure the height to the target (such as electric cable, bridge, etc.) where can't be set prism.



Prism High Known

If the high of prism is known, the calculation formula of the remote height


is:

$$H = S * \cos\alpha_1 * \tan\alpha_2 - S * \sin\alpha_1 + V$$

- 142 -

- Η Height difference between the base point and the remote point
- V Prism High
- Vertical angle to prism α_1
- Vertical angle to target α_2

α_1 Vertical ang	le to prism	
α_2 Vertical ang	le to target	
Steps	Key	Display
(1) Select "Program" from the [Main Menu] window, then press [PAGE] switch to second program list and press [F2] or number key [6] to enter the Area application.	[PAGE] + [F2] or [6]	[Program] 2/3 € F1 Area (5) F2 Remote Height (6) F3 COGO (7) F4 Road (8) F1 F2 F3 F4
(2) After finishing the pre-settings (know more details at the beginning of chapter 5), press [F4] to enter the [Base Pt.] window to start Remote Height app.	[F4]	[Remote Height] [*] F1 Set Job (1) [*] F2 Set STA (2) [*] F3 Set B.S. (3) F4 Start (4) F1 F2 F3 F4



5.10.1 Prism High Unknown


If the high of prism is unknown, the calculation formula of the remote height is:

$$H = S * \cos\alpha_1 * \tan\alpha_2 - S * \sin\alpha_1 * \tan\alpha_3$$

- H Height difference between the base point and the remote point
- V Prism High
- S Slope distance between instrument and prism
- α_1 Vertical angle to prism
- α_2 Vertical angle to target point (remote point)
- α_3 Vertical angle to base point

Steps	Key	Display
 Select "Program" from the [Main Menu] window, then press [PAGE] switch to second program list and press [F2] or number key [6] to enter the Remote Height application. 	[PAGE] + [F2] or [6]	[Program] 2/3 € F1 Area (5) F2 Remote Height (6) F3 COGO (7) F4 Road (8) F1 F2 F3 F4

(2) After finishing the pre-settings (know more details at the beginning of chapter 5), press [F4] to enter the [Base Pt.] window to start Remote Height app.	[F4]	[Remote Height] [*] F1 Set Job (1) [*] F2 Set STA (2) [*] F3 Set B.S. (3) F4 Start (4) F1 F2 F3 F4
(3) In [Base Pt.] window, press [F4] to second page of function keys, then press [F2] (H.T.?) switch to the situation of prism high unknown to start measuring.	[F4] + [F2]	[Base Pt.] Aim and meas. Base PT! Base Pt. : T. H. : 1. 500m ▲ ALL DIST REC EDM H. T. ?



5.11 COGO


COGO(Coordinate Geometry)is an application used to perform coordinate geometry calculations by the preset conditions such as , coordinates of points, bearings between points and distance between points.


The COGO calculation methods include:

- ♦ Inverse and Traverse
- ♦ Intersections
- ♦ Offset
- \diamond Extension

5.11.1 Traverse

Use the traverse sub application to calculate the plane coordinate of a new point using the bearing and distance from a known point. Offset is optional.





Known

- P0 known point
- a Direction from P1 to P2
- d Distance between P1 and P2
- d1 Positive offset to the right
- d2 Negative offset to the left


- P1 COGO point without offset
- P2 COGO point with negative offset
- P3 COGO point with positive offset

Steps	Key	Display
1) Select "Program"		
from the [Main Menu] window, then press [PAGE] switch to second program list and press [F1] or number key [7] to enter the COGO application.	[PAGE] + [F2] or [7]	[Program] 2/3 € F1 Area (5) F2 Remote Height (6) F3 COGO (7) F4 Road (8) F1 F2 F3 F4

 2 After finishing the pre-settings (know more details at the beginning of chapter 5), press [F4] to start COGO app. 	[F4] or [4]	[COGO] [*] F1 Set Job [*] F2 Set STA [*] F3 Set B.S. F4 Start F1 F2 F3	(1) (2) (3) (4) F4
(3) In [COGO Menu] screen, press the [F1] or number key [1] enter the [Traverse & Inverse] screen, press [F2] or [2] enter the traverse sub application.	 [F1] or [1] [F2] or [2] 	[COGO Menu]F1Traverse&InverseF2IntersectionF3OffsetsF4ExtensionF1F2F3[Traverse&Inverse]F1InverseF2TraverseF2Traverse	 (1) (2) (3) (4) F4 (1) (2)

 (4) There are four ways to get the known point for traverse calculation. A: Input the name of known point in "Pt." field in [Traverse] screen and press [F1](Meas.) entry the [COGO Meas] Input prism height in the "T.H." field in 	Input point name + [F1](Meas.) [F1](ALL) or [F2](DIST) +	A: Get the known point by COGO-Meas. [Traverse] Pt. : Azimuth : 15° 34′ 20″ 10. 536m Traverse : 8. 361m Meas. Result Find ↓ List Coord. K- COGO-Meas. [COGO-Meas]
Inc Time field in [COGO-Meas], then aim the prism and press [F1] (ALL) or [F2] (DIST) + [F3] (REC) to measuring and saving the point for traverse calculation.	[F3](REC)	Pt. : 8 T. H. : 1.500m HA : 153° 15′ 10″ VA : 22° 35′ 40″ ALL NEXT PT ↓
B: Press [F1](List) in [Traverse] screen, use the key $[\blacktriangle] [\checkmark]$ to select a Known point in the point list for traverse calculation, then press [F4](OK) to be selected.	[F1](List) + [F4](OK)	B: Select the point by list in the memory. Find Pt.] 1/50 DEFAULT Station STN1 Station 200007 Meas. PT 200008 Meas. PT 100 Fix Pt. 101 Fix Pt. View Coord. Job OK

		1
C: Input the name of		
known point and press		C: Input the name of the point and find
[F3](Find) to find		whether it is in memory.
whether the point is in	Input name	[Find Pt.] 1/3
memory, if exist, then	+	1 Station
press [F4](OK) to be	[F3](Find)	1 Meas. PT
selected for	+	1 Fix Pt.
calculating; if not	[F4](OK)	
exist, then need to		
input or measure the		View Coord. Job OK
point.		
D: Press [F2](Coord.) to input a known point that not exist in memory.	[F2](Coord.) + Input Coord. + [F4](OK)	D: Input the point through keyboard. [Set STA] Job : DEFAULT Pt. : DEFAULT N : O. 000m E : O. 000m Z : O. 000m Back OK
 (5) After setting known point, press [▼]\[▲] key to move focus to the "AZ", " ▲ " and "Transverse" field, 	[▲]\[▼] + Input content + [F2]	[Traverse] Pt. : 8 Azimuth : 15° 34′ 20″ . 10.536m Traverse : 8.361m Meas. Result Find ↓



※ In all of the above operation, press [ESC] to return to the previous screen.※ The result point is plane data.

5.11.2 Inverse

Use the inverse sub application to calculate the distance, direction, height difference between two known points.




Figure 11.2 Inverse Diagram

Known

- P0 First known point
- P1 Second known point

- a Direction from P0 to P1
- S Slope distance between P0 and P1
- d1 Horizontal distance between P0 and P1
- d2 Height difference between P0 and P1

Steps	key	Display
(1) In the [Traverse & Inverse] screen, press [F1] or [1] to enter the Inverse sub application.	[F1] or [1]	[Traverse&Inverse] F1 Inverse (1) F2 Traverse (2) F1 F2
(2) There are four ways to get the known point for inverse calculation.	Input point name +[F1](Meas.)	A: Get the known point by COGO-Meas Inverse Input data! From : PT6 To :
A: Input the name of known point in"Pt." field in [Traverse] screen and press	[F1](ALL) Or [F2](DIST) +	Meas. Result Find ↓ List Coord. ►

[F1](Meas.) entry the	[F3](REC)	
[COGO Meas]		COGO-Meas.
Input prism height in the "T.H." field on [COGO-Meas], then aim the prism and press [F1](ALL) or [F2](DIST) + [F3](REC) to measuring and saving the point for inverse calculation.		[COGO-Meas] Pt. : 8 T. H. : 1.500m HA : 153°15′10″ VA : 22°35′40″ ALL NEXT PT ↓
B: Press [F1](List) in [Traverse] screen, use the key $[\blacktriangle] \ [\checkmark]$ to select a Known point in the point list for inverse calculation, then press [F4](OK) to be done.	[F1](List) + [F4](OK)	B: Select the point by list in the instrument. Find Pt.] 1/50 DEFAULT Station STN1 Station 200007 Meas. PT 200008 Meas. PT 100 Fix Pt. 101 Fix Pt. View Coord. Job OK
C: Input the name of known point and press [F3](Find) to	Input name + [F3](Find)	C: Input the name of the point and find whether it is in memory.

find whether the point is in memory, if	+ [F4](OK)	[Find Pt.]1/31Station
exist, then press [F4](OK) to be		1Meas. PT1Fix Pt.
selected for calculating; if not		
exist, then need to input or measure the		View Coord. Job OK
point.		
D: Press [F2](Coord.) to input a known point that not exist in memory.	[F2](Coord.) + Input Coord. + [F4](OK)	D: Input the point through keyboard. [Input Coord.] Job : DEFAULT Pt. : DEFAULT N : 0.000m E : 0.000m Z : 0.000m Back OK
(3) After setting the first known point then use $[\checkmark] \setminus [\blacktriangle]$ move the focus to "To" field to set the second known point, then press $[F2](Result)$ to	[▼]\[▲]+ [F2]	[Inverse] Input data! From : PT6 To : P7 Meas. Result Find ↓


calculate the inverse point and show the result.				
(4) Input the name of result point in the [Traverse Result] and press [F4](REC) to save the point.	[F4](REC)	[Inverse Form To Azimuth	:	PT6 PT7 34' 43" 2.913m 2.032m 0.561m OK


* In all of the above operation, press [ESC] to return to the previous menu.

* The result point is plane data.

5.11.3 Bearing-Bearing Intersection

Use the bearing-bearing (BRG-BRG) sub application to calculate the intersection point of two lines. A line is defined by a point and a direction.





Known


- P0 First known point
- P1 Second known point
- a1 Direction from P0 to P2
- a2 Direction from P1 to P2

Unknown

P3 COGO point

Steps	key	Display
(1) In [COGO Menu] screen, press the [F2] or number key [2] to enter the [Intersection] screen. Then press [F1] or [1] to enter the BRG-BRG sub application.	[F2] or [2] [F1] or [1]	

 2 Input the name of first point in "PT1" field. ※ There are four ways to get the known point for BRG-BRG calculation. Please refer to the step (2) in the "COGO Traverse". 	Input name of first point	[BRG-BRG] PT1 : 8 AZ1 : 0° 00′ 00″ PT2 : 9 AZ2 : 0° 00′ 00″ Meas. Result Find ↓
③ Move the focus to "AZ1" by using [▼] and input the first bearing after set first point.	[▼] + Input first bearing	[BRG-BRG] PT1 : 8 AZ1 : 26° 15′ 52″ PT2 : 9 AZ2 : 0° 00′ 00″ Meas. Result Find ↓
 ④ Move the focus to "PT2" by using [▼] to setting second point. 	[▼] + Set second point	[BRG-BRG] Input data! PT1 8 AZ1 26° 15′ 52″ PT2 9 AZ2 0° 00′ 00″ Meas. Result




* In all of the above operation, press [ESC] to return to the previous menu.

* The result point is plane data.

5.11.4 Bearing-Distance Intersection

Use the bearing-distance (BRG-DST) sub application to calculate the intersection point of a line and a circle. The line is defined by a point and a

direction. The circle is defined by the center point and the radius. The result may be have 1 intersection point, may be have 2 points, or may be have no one.



- a1 Direction from P0 to P2 or P3
- r Radius, as the distance from P1 to P2 or P3

- P2 First COGO point
- P3 Second COGO point

Steps key	Display
-----------	---------

to enter the BRG-DST subapplication. (2) Input the name of first point in "PT1" field. ** There are four ways to get the known point for BRG-DST calculation. Please refer to the step (2) in the "COGO Traverse".	[2] Input name of first point	PT2 : 9 HD2 : 0.000m Meas. Result Find ↓
③ Move the focus to "AZ1" by using [▼] and input the bearing after set first point.	[▼] + Input bearing	[BRG-DST] Input data! PT1 : 8 AZ1 : 26° 15′ 52″ PT2 : 9 HD2 : 0.000m Meas. Result Find ↓

(4) Move the focus to "PT2" by using [▼] to setting second point.	[▼] + Set second point	[BRG-DST] Input data! PT1 : 8 AZ1 : 26° 15′ 52″ PT2 : 9 HD2 : 0.000m Meas. Result Find ↓
(5) Move the focus to "HD2" by using [▼] and input the radius after set second point.	[▼] + Input radius	[BRG-DST] Input data! PT1 1 PT1 26° 15′ 52″ PT2 9 HD2 12.253m Meas. Result
6 When all of the data are entered correctly, press [F2] (Result) to calculate the intersection point and show the results. Input the name of result point in the [BRG-DST Result] and press [F4](REC) to save the	[F2]	[Brg-Dst Result] Pt. : 10 N : 6.369m E : 3.536m REC

point.		
Press [F1] to switch to		
view results.		

* In all of the above operation, press [ESC] to return to the previous menu.

* The result point is plane data.

5.11.5 Distance-Distance Intersection

Use the distance-distance (DST-DST) sub application to calculate the intersection point of two circles. The circles are defined by the known point as the center point and the distance from the known point to the COGO point as the radius. The result may be have 1 intersection point, may be have 2 points, or may be have no one.




Figure 11.5 DST-DST Diagram


Known

- P1 First known point
- **P**2 Second known point
- Radius, as the distance from P1 to P3 or P4 r1
- Radius, as the distance from P2 to P3 or P4 r2

- P3 First COGO point
- P4 Second COGO point

Симют		
P3 First CO	GO point	
P4 Second C	COGO point	
_	_	
Steps	key	Display
		[Intersection]
1 In the [Intersection]	[F3]	F1BRG-BRG(1)F2BRG-DST(2)
screen, press [F3] or [3] to enter the DST-DST sub application.	or [3]	F3 DST-DST (3) F4 LNLN (4)
one approximition		F1 F2 F3 F4
 2) Input the name of first point in "PT1" field. ※ There are four ways to get the known point for DST-DST calculation. Please refer to the step 	Set first point	[DST-DST]Input data!PT1PT10.000mPT2HD20.000mMeas.ResultFind

(2) in the "COGO Traverse".		
③ Move the focus to "HD1" by using [▼] key and input the first radius after set first point.	[▼] + Input first radius	[DST-DST] Input data! PT1 : 8 HD1 : 3.152m PT2 : 9 HD2 : 0.000m Meas. Result Find ↓
 ④ Move the focus to "PT2" by using [▼] to setting second point. 	[▼] + Set second point	[DST-DST] PT1 : 8 HD1 : 3.152m PT2 : 9 HD2 : 0.000m Meas. Result Find ↓
(5) Move the focus to "HD2" by using [▼] and input the second radius after set second point.	[▼] + Input second radius	[DST-DST] Input data! PT1 : 8 HD1 : 3.152m PT2 : 9 HD2 : 4.654m Meas. Result Find ↓



※ In all of the above operation, press [ESC] to return to the previous menu.※ The result point is plane data.

5.11.6 Line-Line Intersection

Use the line-line (LNLN) sub application to calculate the intersection point of to lines. A line is defined by two points.





Figure 11.6 LNLN Diagram

Known

- P1 First known point
- P2 Second known point
- P3 Third known point
- P4 Fourth known point
- Line from P1 to P2 L1
 - L2 Line from P3 to P4

Unknown

L1 Line from	L1 Line from P1 to P2				
L2 Line from	L2 Line from P3 to P4				
Unknown					
P5 COGO p	oint				
Steps	key	Display			
(1) In the [Intersection] screen, press [F4] or [4] to enter the LNLN sub application.	[F4] or [4]	[Intersection]F1BRG-BRG(1)F2BRG-DST(2)F3DST-DST(3)F4LNLN(4)			
application.		F1 F2 F3 F4			
 2) Set the known point one by one. ※ There are four ways to get the known point for LNLN calculation. Please refer to the step 2 	Set the known points	[LNLN] PT1 : 8 PT2 : 10 PT3 : 9 PT4 : 5 Meas. Result Find ↓			





X In all of the above operation, press [ESC] to return to the previous menu.

* The result point is plane data.

5.11.7 Distance-Offset

Use the distance-offset (DistOff) sub application to calculate the foot point (COGO point) coordinates of offset point to baseline, the baseline is defined by two known points, and the longitudinal and offset distance of the offset point in relation to the line.






Known


- P1 Start point
- P2 End point
- P3 Offset point

Unknown

- d1 △Line
- d2 △Offset
- P4 COGO point (foot point)

Steps	key	y Display		
(1) In [COGO Menu] screen, press the [F3] or number key [3] enter the [Offsets] screen, then press [F1] or [1] enter the DistOff sub application.	[F3] or [3]	[COGO Menu]F1Traverse&Inverse(1)F2Intersection(2)F3Offsets(3)F4Extension(4)F1F2F3F4		





* In all of the above operation, press [ESC] to return to the previous menu.

* The result point is plane data.

5.11.8 Set Point

Use the Set Point (Set Pt) sub application to calculate the coordinate of a new point in relation to a line from known longitudinal and offset distance.





Figure 11.8 Set Point Diagram

Known

- P2 End Point
- d1 \triangle Line
- d2 $\triangle Offset$

Unknown

Unknown		
P3 COGO po	int	
Steps	key	Display
 In the [Offsets] screen, press [F2] or to enter the Set Point sub application. 	[F2] or [2]	[Offsets]F1 DistOffF2 Set PtF1 F2
 2) Set the start point and end point. **There are four ways to get the known point for Set Point calculation. Please refer to the step (2) in the "COGO Traverse". 	Set known points	[Get Side PT] Define baseline! PT1 : 8 PT2 : 9 Input length&trav.! EndW.OS. : 0.000m Transverse : 0.000m Meas. Result Find ↓




X In all of the above operation, press [ESC] to return to the previous menu.

* The result point is plane data.

5.11.9 Extension

Use the Extension sub application to calculate the coordinate of extended

point from a known baseline.





Known


- P1 Baseline Start Point
- P2 Baseline End Point
- L1, L2 Extension Distance

Unknown

P2, P4 Extended COGO Point

Steps	Key Display		
(1) In the [COGO Menu] screen, press the [F4] or number key [4] enter the [Extension] screen.	[F4] or [4]	[COGO Menu]F1Traverse&Inverse(1)F2Intersection(2)F3Offsets(3)F4Extension(4)F1F2F3F4	

 2 Set the baseline start point and end point. ※ There are four ways to get the known point for Extension calculation. Please refer to the step (2) in the "COGO Traverse". 	Set known points	[Extension] Define line! PT1 : 8 PT2 : 9 Select & Input! Base Pt. : 8 HD : 0.000m Meas. Result Find ↓
 (3) Then baseline is defined, press [♥] key to move the focus down and use [◄]\[▶] Key to select base point. 	[▼] + [◀]\[►]	[Extension]Define line!PT1PT2Select & Input!Base Pt.HDConstantMeas.ResultFind
(4) Then press [▼] key to move the focus down and input the extension distance in the "HD" field.	[▼] + Input distance	[Extension]Define line!PT1PT2Select & Input!Base Pt.HD€6.325mMeas.ResultFind



※ In all of the above operation, press [ESC] to return to the previous menu.※ The result point is plane data.

5.12 Road

Road is an application used to measure or stake out points relative to a defined element. The element can be a line, curve or spiral. Chainage, incremental stake outs and offsets(left and right) are supported.


Setting job, setting station and setting backsight must be done before road define and staking out.

[Ro	[Road]				
F1	Road Manage (1)			(1)	
F2				(2)	
F3 Vert. curve list (3)			(3)		
F4	F4 Road Stakeout (4)			(4)	
F	°1	F2	F3	F4	

5.12.1 Road Manage

After setting up the job, station and back sight point, user can start to define the road path.

Steps	Key	Display
(1) Pressing key [F4] to start the road function after job setting, station setting and BS.	[F4]	[Road] [*] F1 Set Job (1) [*] F2 Set STA (2) [*] F3 Set B.S. (3) F4 Start (4) F1 F2 F3 F4
② Pressing key[F1] Road Manage.	[F1]	[Road]F1Road Manage(1)F2HC list(2)F3Vert. curve list(3)F4Road Stakeout(4)F1F2F3F4



5.12.2 HC list

The horizontal curve data can be manually edited, and also be imported from the computer. There are two ways to define the horizontal alignment: one is "element ", another is "intersection".


(1) Define a horizontal alignment by "element method"

The element method consists of the following elements: the starting point,


straight line, circle and easement curve.

Straight line

The straight line can be defined when start point and other type of line have been defined.




Straight line includes azimuth and distance, and the distance cannot be minus.



Circular curve includes radius and arc length. The rules of radius: Along the curve direction, when turning to the right, the radius is positive, negative radius when turning to the left. Arc length cannot be negative.

➢ Easement curve



Easement curve data includes the minimum radius and arc length. The radius positive-negative regularity of easement curve is the same as the radius of circle. Also, the arc length cannot be negative

Follow is the input Steps of the horizontal alignment element method.

► Steps

Operating procedure	Key		Display
(1) Choose "2.HC list" from the road menu.	"2. list"	НС	HC list I L C C

		Hoizon curve
(2) Press 【ADD】 . If you haven't input starting point, you will come in starting point interface whatever straight line, circular curve or easement curve you choose. Input the start point and press 【OK】.	【ADD】 【OK】	Chain.: 0.000 AZ: 0° 00' 00" STR ARC TRNS PT Define start point ••••••••••••••••••••••••••••••••••••
(3)Press [STR] come in the straight line data input screen. When completed setting, press [OK] .	(STR)	Define Straight L I AZ: 0.000 Dist: 200.000 m OK
(4) Press 【ARC】 come in the circular curve data input interface. When completed setting ,press 【OK】 .	【ARC】	HC-arc *** R: 240.000 Length: 250.000 OK

(5) Press 【 TRNS 】 come in the easement curve data input interface.	【TRNS】	HC-transition R: 214.000 Length: 200.000 m OK
(6) Complete setting all line data, press [ESC] return to horizontal alignment list interface.	[ESC]	HC list Image: Left for the list 01Start: 0.000 02STR: 0.000 03ARC: 200.000 04TRNS: 450.000 SAVE DEL. ADD VIEW
 (7) Press 【VIEW】 to show the road data of the line you chosen. Here we choose the circular curve as an example. You can view the road date in the list according to 【▼】 【▲】. Press 【EDIT】 to edit the road data. 	【VIEW】	edit-arc Image: Len.th R: 240.000 Len.th 250.000 m EDIT PREV NEXT
(8)Press 【ADD】 to add new road data.	【ADD】	Hoizon curve ILON Hoizon curve -4 Chain.: 0.000 AZ: 0° 00′ 00″ STR ARC TRNS


(9) Press 【DEL.】 to delete the chosen line date (start point is forbidden).	【DEL.】	HC list Image: Constraint in the second
(10) Press [SAVE] to get a prompt box, press [ENT] to save the data in the current opened road file.	[SAVE]	HC list

Note: If you don't save the data, there will be no data or the data existent earlier in the road file when you restart the total station.

(2) Define the horizontal alignment by "intersection method"

The intersection of point includes coordinate, radius and parameters A1,A2 of the easement curve. The radius and parameters A1, A2 can't be minus. If inputting radius there will be inserted an arc with a specified radius between the current point and the next point. If inputting easement curve and parameters A1, A2 there will be inserted an easement curve with a specified length between the straight line and the arc.

Don't mix the point of intersection with the straight line, arc and easement curve, or the calculation will be wrong.



Follow is the Intersection method definition of horizontal alignment input Steps.

► Steps

Operating procedure	Key	Display
(1) Choose "2. HC list" from the road menu.	"2. HC list"	HC list Image: Constraint of the second
(2) Press 【ADD】 come in line choose interface . If you haven't input starting point, you will come in starting point interface.	【ADD】 【OK】	Define start point L Chain. 0.000 N: 200.000 m E: 300.000 OK

(3) Input start point, then press 【OK】 come in the point of intersection input interface. Press 【OK】 to input the next point of intersection.	[0K]	N:(P1) 99.835 E: 149.008 R: 0.710 m AZ1: 32.0000 AZ2: 300.000 OK
 (4) After input all points of intersection press [ESC] return to horizontal alignment list interface. It is line + N coordinate of the intersection in the list. 	[ESC]	HC list * • • • • • 01Start: 0.000 02PT: 214.000 03PT: 574.000 04PT: 637.000 SAVE DEL. ADD VIEW
 (5) Press 【VIEW】 to show the detail data of the current road you chosen. You can view the road date in the list according to 【 → 】 or 【 → 】 Press 【EDIT】 to edit the road data, the operation is the same as the input. 		N: 99.835 E: 149.008 R: 0.710 m AZ1: 32.0000 AZ2: 300.000 EDIT PREV
(6)Press 【ADD】 to continue to add new road data.	【ADD】	Horizon curve

(7) Press (DEL.) to delete the line date chosen(start point is forbidden).	(DEL.)	HC list 01Start: 02PT: 03PT: SAVE DEL	 ■ ■ ■ 0.000 214.000 574.000 ■ ADD VIEW
(8) Press [SAVE] to get a prompt box , press [ENT] to save the data in the current opened road file.	【SAVE】	HC list Save ove	∦ ⊥ © [r!


Note: Use the following formula to compute when you input A1,A2 according to L1, L2.

 $A_{1} = \sqrt{L_{1} \cdot radius}$ $A_{2} = \sqrt{L_{2} \cdot radius}$

You can edit the alignment just according to the alignment menu.

5.12.3 Vert.curve list

Vertical alignment consists of a set of intersection points. Intersection point including pile number, height and the curve length. The curve length of starting point and end point of vertical alignment must be zero.



Chain	1000	1300	1800	2300
Elevation	50	70	60	90
Lenth	0	300	300	0

Following is the vertical alignment input Steps.

►Steps

Operating procedure	Кеу	Display
(1) Choose "3. VC list" from the road menu.	"3. VC list"	
(2) Press 【ADD】 come in line choose interface. After input data, press 【OK】 to input the next point.	【ADD】	VC-start point L I Chain: 0.000 0 Elevat. 200.000 m Len.: 300.000 OK

(3) After input line data, press [ESC] return to vertical alignment list interface.	【OK】	VC list Image: Constraint for the second s
 (4) Press 【VIEW】 to show the detail data of the current road you chosen. You can view the road date in the list according to 【▼】【▲】 Press 【EDIT】 to edit the road data, the operation is the same as the input.₀ 	【VIEW】	VD LIST-01 Image: I
(5) Press 【ADD】 to continue to add new road data.	【ADD】	VD LIST-04 Chain: 0.000 Elevat. 200.000 m Len.: 300.000 OK
(6) Press 【DEL.】 to delete the line date chosen(start point is forbidden).	【DEL.】	VC list 0.000 01Start : 0.000 02PT: 98.000 SAVE DEL. ADD VIEW

5.12.4 Road Stakeout

After the road had been designed and had been implemented into the program, user can start to do road stakeout.

Steps	Key	Display
1 In Road program, click F2 Road Stakeout to enter the function.	[F2]	[Road]F1Define road path(1)F2Road Stakeout(2)F3Result. Setting out(3)F4Transfer(4)F1F2F3F4

 (2) Pressing F1 Sidestake Stakout to go for sidestake stakeout interface. Input the chainage and the coordinates of the points that should be stakeout will be loaded and you will start the staking job. [T.H]:Target height [Increment]: Interval between to stakes. [Offset]: the offset to the center stake, left is negative while right is positive. 	[F1]	[Sidestake stakeout] 1/3- Chainage 0.000 m T. H. 0.000 m Azimuth 0.000 m Back 0.000 m Offset lef: 0.000 m Meas. REC EDM
--	------	---

5.13 Stakeout Reference Element


Stakeout Reference Element is used for making Reference Element stakeout and check easier, such as building, road cross section, or simple excavation. User can define a Reference Line/ARC, according to measuring result, to calculate out the deviated difference& elevation difference between measuring point and reference line/arc. Reference element function include:

- ♦ RefLine
- \diamond RefArc
- ♦ RefSurface


5.13.1 RefLine

User need to define a reference line through a known base line. The reference line can be shifted in longitudinal, horizontal, vertical direction, or rotate around the first base point as needed. The line after shift is as reference line, all observed data refer reference line. User can choose the first point, second point or mean point in refline direction as referred elevation point.

Refline schematic diagram:




- p Measure point
- d3 \triangle Length
- d4 \triangle trav.
- Reference Line




enter		
RefLine		
function.		
		\odot
2		
There're		
several		A: Get the target point by measure.
methods		
to obtain		[Reference Line] 1/2 Measure to first point!
the first	Input	
point for	point	
baseline	name	T. H. : 2. 000m 10. 536m
definition	+	∠ : 8.361m
	[F1]	ALL DIST REC 🗸
A: Enter		Find List Coord. ↓
point		EDM 🛏
name,		
then		
press		

[F1](AL		
L) to		
define		
first		(c)
point.		
B: Input		
point		5
name,		
Press		
[F2](DIS		B: Get the target point by DIST+REC.
T) +		[Reference Line] 1/2 🗸
[F3](RE		Measure to first point!
C) to		PT1 : .
save	[F2]	T. H. : 2. 000m
target	+	10. 536m
point, the	[F3]	─ : 8.361m
saved		ALL DIST REC
result		Find List Coord.
will be		EDM 🛏
directly		
put into		
calculatio		
n.		



through $[\blacktriangle] \setminus [\checkmark]$ and press [F4](OK) to select. E: Press [F3](Coo rd.), input point name, coordinat e data and press [F4](OK) to select. E: Input the point through keyboard. [F3] + Input point name, coordinat e data and press [F4](OK)			
[Find Pt.]STNDStationdialog, searchSTNDStationgeneration200007Meas. PT200008Meas. PT100Fix Pt.101Fix Pt.102Coord.JobOK103Fix Pt.104Fix Pt.104Fix Pt.105DEFAULT106DEFAULT107Pt.108O.000m109Toord.100Fix Pt.100Fix Pt.101Fix Pt.101Fix Pt.102DEFAULT103Pt.104Pt.105DEFAULT106O.000m107Toord.108Toord.109Toord.100Toord.100Toord.100Toord.100Toord.100Toord.100Toord.100Toord.100Toord.100Toord.100Toord.100Toord.100Toord.100Toord.	[F2](List)	+	[Find Pt.] 1/50
$\begin{array}{cccccccccccccccccccccccccccccccccccc$, in	[F4]	DEFAULT Station
dialog, search 200008 Meas. PT 100 Fix Pt.the known 200008 Meas. PT 101 Fix Pt.knownViewCoord.Jobpoints in jobViewCoord.Jobjob through [\blacktriangle]N[\checkmark] and pressE: Input the point through keyboard.[F3](Coo rd.), input point name, coordinat e data and pressE: Input the point through keyboard.[F3](Coo rd.), input point name, coordinat and press te+E: Input the point through keyboard.[F3](Coo rd.), input point name, coordinat and press te+E: Input the point through keyboard.	[Find Pt.]		
search the known points in job through $[\land \mathbb{N}[\lor]$ and press [F4](OK) to select. E: Press [F3](Coo rd.), input point name, coordinat e data and press $[F4](OK)to select.E: Input the point through keyboard.[F3] = DEFAULTPt.DEFAULTPt.DEFAULTPt.DEFAULTPt.DEFAULTPt.DEFAULTPt.O. 000mZO. 000m$	dialog,		
the known points in job through $[\blacktriangle] [101 Fix Pt.$ View Coord. Job OK View Coord. Job OK ($ \bigtriangleup] [101 Fix Pt.$ View Coord. Job OK ($ \Biggr] [101 Fix Pt.$ View Coord. Job OK ($ \Biggr] [101 Fix Pt.$ View Coord. Job OK ($ \Biggr] [101 Fix Pt.$ View Coord. Job OK ($ \Biggr] [101 Fix Pt.$ View Coord. Job OK ($ \Biggr] [101 Fix Pt.$ View Coord. Job OK ($ \Biggr] [101 Fix Pt.$ View Coord. Job OK ($ \Biggr] [101 Fix Pt.$ View Coord. Job OK ($ \Biggr] [101 Fix Pt.$ View Coord. Job OK ($ \Biggr] [101 Fix Pt.$ View Coord. Job OK ($ \Biggr] [101 Fix Pt.$ View Coord. Job OK ($ \Biggr] [101 Fix Pt.$ View Coord. Job OK ($ \Biggr] [101 Fix Pt.$ View Coord. Job OK ($ \Biggr] [101 Fix Pt.$ View Coord. Job OK ($ \Biggr] [101 Fix Pt.$ View Coord. Job OK ($ \Biggr] [101 Fix Pt.$ DEFAULT ($ \Biggr] [101 Fix P$	search		
points in job through []] [V] and press [F4](OK) to select. E: Press [F3](Coo rd.), input point name, coordinat e data and press $[F4](OK)to select.E: Input the point through keyboard.[F3] = E:$ Input the point through keyboard. [F3] = E: Input the point through keyboard. [F4] = E: Input the point through keyboard. [F3] = E: Input the point through keyboard. [F4] = E: Input the point through keyboard. [F3] = E: Input the point through keyboard. [F4] = E: Input the point through keyboard. [F3] = E: Input the point through keyboard.	the		
job through $[▲] \setminus [♥]$ and press [F4](OK) to select. E: Press [F3](Coo rd.), input point name, coordinat e data and press $[F4](OK)to select.E: Input the point through keyboard.[Input Coord.]DEFAULTN : DEFAULTN : DEFAULTN : 0.000mE : 0.000mE : 0.000m$	known		View Coord. Job OK
through $[\blacktriangle] \setminus [\checkmark]$ and press [F4](OK) to select. E: Press [F3](Coo rd.), input point name, coordinat e data and press [F4](OK) to select. E: Input the point through keyboard. [F3] + Input point name, coordinat e data and press [F4](OK)	points in		
$\begin{bmatrix} \mathbf{A} \\ \mathbf{N} \\ \mathbf{V} \end{bmatrix}$ and press $\begin{bmatrix} F4 \\ \mathbf{O} \\ \mathbf{K} \\ \mathbf{V} \\$	job		
and press [F4](OK) to select. E: Press [F3](Coo rd.), input point name, coordinat e data and press [F4](OK) + Input point name, coordinat e data and press [F4](OK) + H H H H H H H H H H H H H	through		
[F4](OK) to select. E: Press [F3](Coo rd.), input point name, coordinat e data and press LF4(OK)	[▲]\[▼]		
to select. E: Press [F3](Coo rd.), input point name, coordinat e data and press LL 1/(OVI) E: Input the point through keyboard. E: Input the point through keyboard. Input Coord. Job : DEFAULT N : O.000m Z : O.000m	and press		
E: Press [F3](Coo rd.), input point name, coordinat e data and press LE: Input the point through keyboard. E: Input Coord.] DEFAULT N : DEFAULT N : 0.000m E : 0.000m Z : 0.000m	[F4](OK)		
[F3](Coo [F3] E: Input the point through keyboard. rd.), input + [Input Coord.] point Input Job : DEFAULT name, point N coordinat name 0.000m and press te+ Input	to select.		
[F3](Coo [F3] E: Input the point through keyboard. rd.), input + [Input Coord.] point Input Job : DEFAULT name, point N coordinat name 0.000m and press te+ Input			
rd.), input point name, e data and press LL 1/(OLO) rd.), input point name, e data and press LL 1/(OLO) rd.), input point name, e data and press LL 1/(OLO) rd.), input point name, e data rd.), input point name, e data rd.), input point name, rd.), input point name, rd.), input point name, rd.), input point name, rd.), input point name rd.), input point rd.), input point rd.), input point rd.), input point rd.), input point rd.), input point rd.), input point rd.), input point rd.), input rd.), input point rd.), input rd.), in	E: Press		
rd.), input point name, coordinat e data and press LT41(OV) rd.) rd.) true	[F3](Coo		E: Input the point through keyboard
pointInputJobDEFAULTname,pointPt.DEFAULTpointN0.000mnameE0.000medataZ0.000mand presste+Image: Constant of the second s	rd.), input		
name, coordinat e data and press LEAL(OVI) Pt. : DEFAULT N : 0.000m E : 0.000m Z : 0.000m	point		
coordinat e data and press te+	name,		Ď ·
coordina and press te+	coordinat	-	N : $0.000m$
and press te+	e data		E : 0.000m 7 0.000m
te+	and press		
	[F4](OK)		Back OK
, it will [F4] Back OK		[F4]	
indicate	indicate		

cover if		
the point		
name is		$\langle \Theta \rangle$
repeated.		
3		
After	[F1]	
defining	or	
first point	[F2]+[F	[Reference Line] $1/2$ -
of	3]	Measure to first point! 🛄
baseline,	or	PT1 : 2
enter into	[F4]+[F	T. H. : $2.000m$
interface	1]	∠ : 10.536m
of second	or	
point	[F4]+[F	ALL DIST REC
definition	2]	Find List Coord. ↓
, the way	or	EDM K-
is same	[F4]+[F	
as with	3]	
first		
point.		



	[]
e	
Line-Mai	
n] page,	
press	\odot
[◀]\[▶]	
to choose	
Ref.Hgt,	
after set	
up. Ж ¹	
⑤ In the	
interface	
of	
[Referenc	
e	
Line-Mai	[Reference Line-Main]1/2 _ Length : 360.555m
n], if	Enter values to shift line!
baseline [F4]	Offs <mark>et</mark> : <u>5.000m</u>
needs to +	Line : 2.000m
be [F1]	Height : <u>10.536m</u> Rotate : <u>1°02'03"</u>
redefined	Gird Meas. Stake
, press	NewBL Zero Segment ←
[F4](↓)	Hender Dero besmente n
to shift to	
subscript	
function	
and press	

[F1]		
(NewBL)		
to		
redefine		\odot
new		
baseline.		
6 In the		
interface		
of		
[Referenc		
e		
Line-Mai		
n], input		[Reference Line-Main]2/2 -
translatio		PT1 : 1
n	[F4]	PT2 : 2 Length : 360.555m
paramete		Enter values to shift line!
rs, if you	+	Ref. <mark>Hg</mark> t : PT1 ↔
need to	[F2]	
clear,		Gird Meas. Stake ↓
press [F4]		NewBL Zero Segment I←
(↓) to		
shift		V
subscript		
function,		
press		
[F2]		


(Zero) to	
recover	
input	
paramete	\odot
rs to zero.	

 $\%^1$ Ref.Hgt options :

- PT1 : The elevation value of defined first point
- PT2 : The elevation value of defined second point
- Equal : Average value of defined two endpoints' elevation
- None : Not perform elevation difference calculation
- * In above operation, press [ESC] to return to previous menu

• Stakeout Grid

Steps	Key	Display	
(1) In the interface of [Reference Line-Main], press [F1] (Gird) to enter the [Grid Definition].		[Reference Line-Main]1/2Length:360.555mEnter values to shift line!Offset:0ffset:0.000mLine:2.000mHeight:10.536mRotate:1° 02' 03"GirdMeas.Stake	



* In above operations, press [ESC] to return to previous menu.

Measure Line&Offset

 In interface of [Reference Line-Main], press [F2] (Meas.) to [F2] enter [Measure Line&Offset] interface. 	[Reference Line-Main]1/2Length :360.555mEnter values to shift line!Offset :5.000mLine :2.000mHeight :10.536mRotate :1° 02′ 03″Gird Meas.StakeNewBLZeroSegmentI←
 2 There are many methods to obtain points for calculating Line&Offset Line&Offset Input A: Input the name of point, press [F1](ALL) to measure current point, calculate and display the offset to refline , then save this point data. 	A: Get the target point by measure. Measure Line&Offset Pt. : 4 T. H. : 2.000m ALength : 3.369m ATrav. : 1.147m A 1.256m ALL DIST REC ↓
B: Input point name, press [F2] (DIST) to measure target point, calculate and display this point's offset to refline, then press	B: Get the target point by DIST+REC.

[F3](REC) to save this point data.		[Measure Line&Offset] Pt. : 4 T. H. : 2.000m △Length : 3.369m △Trav. : 1.147m △ : 1.256m ALL DIST REC
C: Input the name of known point and press $[F4](\downarrow)$ to shift to subscript function, then press $[F3](Find)$ to find whether the point is in memory, if exist, then press $[F4](OK)$ to be selected for calculating; if not exist, then need to input or measure the point.	name + [F4] + [F1] +	C: Input the name of the point and find whether it is in memory. Find Pt.] 1/3 1 Station 1 Meas. PT 1 Fix Pt. View Coord. Job OK
D: Press [F2] (List) in [Find Pt.] screen, use the key [\blacktriangle]\[\checkmark] to select a known point in the point list for traverse calculation, then press [F4](OK) to		D: Select the point by list in the instrument.

be selected.		[Find Pt.]1/50DEFAULTStationSTN1Station200007Meas. PT200008Meas. PT100Fix Pt.101Fix Pt.ViewCoord.JobOK
E: Press [F3](Coord.) to input a known point		E: Input the point through keyboard. [Input Coord.] Job : DEFAULT Pt. : DEFAULT
	name coordinate+ [F4]	N : 0.000m E : 0.000m Z : 0.000m Back 0K

* In above operation, press [ESC] to return to previous menu.

Orthogonal stakeout


Steps	Key	Display
Image: 1Image: 1Image: 1Image: 2Image: 1Image: 2Image: 2 <td>[F1]</td> <td>[Reference Line-Main]1/2Length :360.555mEnter values to shift line!Offset :5.000mLine :2.000mHeight :10.536mRotate :1° 02′ 03″Gird Meas.StakeNewBLZeroSegmentI←</td>	[F1]	[Reference Line-Main]1/2Length :360.555mEnter values to shift line!Offset :5.000mLine :2.000mHeight :10.536mRotate :1° 02′ 03″Gird Meas.StakeNewBLZeroSegmentI←
② In interface of	[▲]\[▼]	

[Orthogonal Stakeout]	+	
use $[\blacktriangle] [\lor]$ to select	Input	
input box, use keyboard	parameters	
to set every offset	+	\odot
parameters, then press	[F4]	
[F4](OK) to enter		
orthogonal stakeout.		
 ③ In [Orthg. Stakeout] interface, measure and save current measuring point through [F1](ALL) or [F2]+[F3](DIST+REC), 	[F1] or [F2]+[F3]	$\begin{bmatrix} \text{Orthog. Stakeout} & 1/2 \\ \text{Pt.} & \vdots & 3 \\ \text{T. H.} & \vdots & 2.000m \\ & & & & \\ & & & \\ & & & & \\ & & & \\ & &$
and it will return to [Orthogonal Stakeout] screen.		ALL DIST REC ↓ NEXT PT EDM Back ←

* In above operation, press [ESC] to return to previous menu.

• Segment stakeout

Steps	Key	Display
(1) In		[Reference Line-Main]1/2 _ Length : 360.555m
[Reference	[F4]	Enter values to shift line! Offset : 5.000m
Line-Main]	+	Line : <u>2.000m</u> Height : <u>10.536m</u>
screen, press	[F1]	Rotate : $1^{\circ} 02' 03''$
$[F4](\downarrow)$ and		Gird Meas. Stake ↓
Press [F3] to		NewBL Zero Segment 🛏



[F1](ALL)or	[Stakeout Segment] 2/2 -
[F2]+[F3](DIS	Pt. : 3 🚺
T+REC)	Cum. Length: 0.555m 🔶 😤
,	Number : 1 🔶 🕎
	∆Length ↑ 130.644m
	∆Trav. ← -52.216m
	<u>∧</u>
	ALL DIST REC EDM

 $\%^1$ Segment options:

Start : Misclosure at the start point

EndPt : Misclosure at the end point

Equal : Divide Reference Line equally into several pieces


* In above operation, press [ESC] to return to previous menu.


5.13.2 RefArc


RefArc can be defined through "Centre, Start Point" or "Start&End Pt, Angle", and you can calculate Line&Offset of point to refarc. The application program allow user define a refarc and finish below task about refarc:


• Measure Line&Offset


RefArc schematic diagram:














r	1	
press [F1](Fi		
nd) to		$\langle \mathbf{e} \rangle$
check		
if this		
point		
exists,		
if not		
exist,		
then		
should		
firstly		
input		
or		
measur		GEDBDL
ing		
this		
point's		
coordi		
nate.		
D:		
Press		
[F2](Li	[F2]	
st), in	+	D: Select the point by list in the instrument.
[Find	[F4]	
Pt.]		

[Find Pt.] 1/50	
DEFAULT Station	
	Ð
101 Fix Pt.	
View Coord. Job OK	
	>
E: Input the point through keyboard.	
t Pt. : DEFAULT	
$\begin{array}{c c} \mathbf{d} \\ \mathbf{Z} \\ \vdots \\ 0.000 \mathbf{m} \end{array}$	
Back OK	
n n or	BI E: Input the point through keyboard. Interface Input Coord. Job DEFAULT Station 200007 Meas. PT 200008 Meas. PT 100 Fix Pt. 101 Ion Fix Pt. View Coord. Job OK

	1	
will		
indicat		
e		
recover		\odot
if point		
name		
is		
repeate		
d, then		
press		
[F4](O		
K) to		
save		
the		
point.		
4	[F1]	
After	or	[RefArc] $1/2$
measur	[F2]+	Measu <mark>re</mark> to start point!
ing	[F3]	Start : 2.000m
centre	or	10.536m
point,	[F4]+	- : 8.361m [▲]
you	[F1]	ALL DIST REC
can	or	Find List Coord.
measur	[F4]+	EDM K
e the	[F2]	
start	or	


point,	[F4]+	
the	[F3]	
definiti		
on is		S
same		
as		
centre		
point.		
\mathbb{X}^1		
5		
After		
definiti		[Reference ARC-Main Page]
on of		CtrPt : Start : 2
RefArc		Start : 2 EndPt : 3
, enter	[F4]	Radius : 5.584m
interfa		
ce of		NewArra
[Refere		NewArc Meas.
nce		[Measure Line&offset]
ARC-		Pt. : 4 T. H. : 2.000m
Main		△Line : 130.644m
Page];		∆Offset : -52.216m
0.17		△ : -8.188m
	[F1]	
	r 1	ALL DIST REC 🕹
Press		


[F4](M	
eas.) to	Measure to start point! Start :
enter	T. H. : 2. 000m
[Measu	■ : 10.536m · 8.361m
re	→ : 8.361m
Line&	ALL DIST REC 🕹
Offset]	Find List Coord. ↓
interfa	EDM K-
ce;	
If it	
needs	
to	
define	
a new	
RefArc	
,	
press	
[F1](N	
ewArc)	
to	
define.	


 $\%^1$ When the centre and start point coincide, the system error reporting "invalid target data, please input again, select "yes" or press [ESC], return to the measurement center interface, and restart the definition of arc.


X In above operation, press [ESC] to return to previous menu.


• Start&End Pt, Angle
















[F1](Fi	
nd) to	
check	
if this	\odot
point	
exists,	
if not	
exist,	
then	
should	
firstly	
input	
or	GEDBOY
measur	
e this	
point's	
coordi	
nate.	
D:	D: Select the point by list in the instrument.
Press	[Find Pt.] 1/50
[F2](Li	DEFAULT Station
st), in	51111 Station
[Find +	200007 Meas. PT 200008 Meas. PT
Pt.]	100 Fix Pt.
screen,	101 Fix Pt.
search	View Coord. Job OK











press				
[F1](N ewArc)				
ewArc)				
to				
define.				

 $\%^1$ AZ1 and AZ2 are start point, end point tangent azimuth respectively. If the input data is not in conformity with the requirements, the instrument will report "invalid target data, please input again", you can select "yes" or press the [ESC] to return to the interface of starting point measurement, start to define arc.

% In above operation, press [ESC] to return to previous menu.

• Measure Line&Offset

Steps Rey Display

(1) Using method of the "Centre, Start Point" or "Start&End Pt, Angle" defines the reference arc, entering the [Reference ARC-Main Page], and press [F4] (Meas.) to Measure Line&Offset	[F4]	[Reference ARC-Main Page] CtrPt Start Start 2 EndPt 3 Radius 5.584m NewArc Meas. [Measure Line&offset] Pt. 1 Pt. 2 Offset -52.216m ALL ALL DIST
 ② There are several methods to obtain the Pt which is used for Measure Line&Offset A: Enter point name, then press [F1](ALL) to define the Pt. 	Input point name + [F1]	A: Get the target point by measure. $\begin{bmatrix} Measure Line&offset \end{bmatrix}$ Pt. : 4 T. H. : 2.000m $\triangle Line$: 130.644m $\triangle 0ffset$: -52.216m $\triangle -8.188m$ ALL DIST REC \downarrow

B: Input point name, Press [F2](DIST) + [F3](REC) to save the Pt, the saved result will be directly put into calculation.	[F2] + [F3]	B: Get the target point by DIST+REC. [Measure Line&offset] Pt. : 4 T. H. : 2.000m △Line : 130.644m △Offset : -52.216m △ ▲ : -8.188m ALL DIST REC ↓
C: Input point name, press $[F4](\downarrow)$ to shift to subscript function, press $[F1](Find)$ to check whether this point was existed, if not exist, then should firstly input or measuring this point's coordinate.	Input point name + [F4] + [F1] + [F4]	C: Input the name of the point and find whether it is in memory. Find Pt.] 1/3 1 Station 1 Meas. PT 1 Fix Pt. View Coord. Job OK
D: Press [F2](List) , in [Find Pt.] screen, search the known points in job through [\blacktriangle]\[\checkmark] and press [F4](OK) to select.	[F2] + [F4]	D: Select the point by list in the instrument.

		[Find Pt.]1/50DEFAULTStationSTN1Station200007Meas. PT200008Meas. PT100Fix Pt.101Fix Pt.ViewCoord.JobOK
E: Press [F3](Coord.), Input point name, coordinate's data, it will indicate recover if point name is repeated, then press [F4](OK) to save the point.	[F3] + Input point name coordinate + [F4]	E: Input the point through keyboard. Input Coord.] Job : DEFAULT Pt. : DEFAULT N : O. 000m E : O. 000m Z : O. 000m Back OK
(3) After measuring points in different ways, we can see the result of the high deviation, Δ Line and Δ Offset. \approx^{1}		[Measure Line&offset] Pt. :4 T.H. :2.000m △Line : 130.644m △Offset : -52.216m △ : -8.188m ALL DIST REC ↓

 $\%^1$ Result of Line&Offset:

 Δ Line: Measuring point relative to the start point of arc , if it is beyond the

reference arc , Δ Line will be negative, and on the contrary is positive;

 Δ Offset: the offset of the measuring point with respect to the arc in the

direction of the radius. If the measuring point is in the circle, the Δ Offset will be positive, and on the contrary is negative.

△ ▲: the elevation difference between measuring point and starting point; If it is higher than start point, it will be positive, and on the contrary is negative.
※ In above operation, press [ESC] to return to previous menu.


5.13.3 RefSurface

Reference Surface is also known as Reference Plane. It is a function that can be used to measure points relative to a reference plane. It can be used to:

- Measuring a point to calculate and store the perpendicular offset to the plane
- Calculating the perpendicular distance form the intersection point to the local X and Z axis. The intersection point is the footprint point of the perpendicular vector from the measured point through the defined plane.
- Viewing, storing and staking out the coordinates of the intersection point.

A reference plane is created by measuring three points on a plane. These three points define a local coordinate system:

- The first point is the origin of a local coordinate system.
- The second point defines the direction of the local Z-axis.
- The third point defines the plane.



X-axis of local coordinate system.

- Y-axis of local coordinate system.
- Z-axis of local coordinate system.
- P1 First point, origin of local coordinate system.
- P2 Second point
- P3 Third point

P4 Measured point. This point is prob- ably not located on the plane.

P5 Footprint point of the perpendicular vector from P4 to the defined plane. This point is definitely located on the defined plane. d+ Perpendicular distance from P4 to the plane.

Functions that can be done by the software buttons:

[New-tar]: To record and save the intersection point and to proceed to measure a new target point.

[Stakeout]: To display stake out values for the intersection point.


[New-sur]: To define a new reference plane.

[Done]: to go back to the program menu.

[Refsur	face re	sult]	1/2
PT	:		12
Offset	:	1.(005 m
ΔX	:	11.8	893 m
∆PT		4. '	781 m
New-tar	Stakeout	New-sur	Done

6 File manage

File manager contains all functions of input data, edit data and view data.



6.1 Job

- All kinds of measurement data are saved in the selected job. Such as Fix Pt., Meas. PT and so on.
- > The function can new a job, select a job and delete a job.
- The definition of the job contains the inputting of Job's name and Operator.

6.1.1 Select a Job

Steps	Key	Display
(1) Press [F1] in the menu of Job Manager to enter menu of job function.	[F1]	[Job Manage] 1/2 - F1 Job (1) F2 Fix Pt. (2) F3 Meas. PT (3) F4 Code (4) F1 F2 F3 F4
2 The interface displays the job list in the current storage.		[Job list] JOB1 * JOB2 JOB3 JOB4 Delete New View OK
(3) Using the direction keys to select a job, when the needed job is selected, press the key of [F4], the program gives a prompt of "Job Set" and open the job as the current job.	[↑]、 [↓] + [F4]	[Job list] JOB1 IOB2 * JOB3 JOB4 Delete New View OK

6.1.2 New a Job

Steps	Key	Display
 In the menu of Job Manager, press [F1] to enter the menu of job function. 	[F1]	[Job Manage] 1/2 - F1 Job (1) F2 Fix Pt. (2) F3 Meas. PT (3) F4 Code (4) F1 F2 F3 F4
(2) The interface displays the job list in the current storage. The jobs in the SD card have the mark of "[SD]" and the current job have the mark of "*". Press [F2] (New) to enter the function of new a job.		[Job list] JOB1 * JOB2 JOB3 [SD] JOB4 [SD] Delete New View OK

 (3) If the instrument has loaded the SD card, there is an interface of Select Disk. In the interface, selecting the disk which is used to new a job by pressing the key of up or down and press [F4] to make sure. A:Local Disk B:SD Card 		[Select Disk] A:Local Disk B:SD Card Prop. OK
(4) The screen displays the information of new job, including the name of the job, the operator and so on. After inputting one item, press [ENT] to move the cursor to the next input area. ^{*1}	[ENT]	[New Job] Job : Job : Operator : Note1 : Note2 : Date : 2015.05.15 Time : 14:10:20 Back 0K

(5) After finishing inputting, press [F4] (OK) to save the job and set it as the current job.	Job set!
---	----------

 $\%^1$: The system creates the data and time automatically.

[Job]: The name of job inputted arbitrarily by the operator and saving data to the file after this.

[Operator]: The name of operator and it can have the default value.

[Note1] and [Note2] describe the situation of the project and they can have the default values.

If the job name you inputted exists, the program will give a prompt that Job exists, use another job name.

Steps	Key	Display		
(1) In the menu of Job Manager, press [F1] to enter the menu of job function.	[F1]	[Job Manage] F1 Job F2 Fix Pt. F3 Meas. PT F4 Code F1 F2 F3	1/2 - (1) (2) (3) (4) F4	

6.1.3 Delete a job

2 The interface displays the job list in the current storage.		[Job list] JOB1 * JOB2 JOB3 JOB4 Delete New View OK
 ③ Using the direction key up or down to select the job that need to be deleted. Press [F1] (Delete) and a dialog appears as shown in the picture on the right. If you make sure to delete it, please press [F4] (Yes), otherwise, press [F1] (No) to back to the previous menu. ※¹ 	[↑]、 [↓] + [F1] + [F4]	Sure to delete job? Data cannot recover! No Yes
^{*1} : The current job can't	t be deleted.	

6.2 Fix Pt.

The function can view, edit and delete the fixpoints in all jobs.

Steps	Key	Display
(1) In the menu of Job Manager, press [F2] to enter the interface of Fix Pt. function.	[F2]	[Job Manage] 1/2 - F1 Job (1) F2 Fix Pt. (2) F3 Meas. PT (3) F4 Code (4) F1 F2 F3 F4
(2) The interface displays the fixpoints of the current job. Pressing the direction key of left or right can scan all fixpoints in the job. Press [F4] to switch to the second page' soft key.	[F4] + [F2]	[View FixPoint] 1/4 Job : JOB1 Pt. : 6<
(3) Press [F2](Job) to enter the list of job, press the direction key of up or down to select the job which the viewed fixpoints exist, then press [F4] to make	[F4]	[Job list] JOB1 * A JOB2 JOB3 [SD] JOB4 [SD] Delete New View OK


sure. ^{%1}				
(4) Program displays the data of fixpoints in the corresponding job. Press the direction key of left or right can view all fixpoints in the job.	[←] [→]	[View Fi Job Pt. N E Z Delete	ixPoint : : : : Job	t] 1/22 JOB2 C P1 2. 000m 3. 000m 4. 000m

 \times^1 : The selected job is only used to view fixpoints and it will not be set as current job.

6.2.1 Search Fix Pt.


Input the name of point or "*" to view the fixpoints in the selected job.


Steps	Key	Display
(1) In the interface of View FixPoints, pressing [F1] (Find) to enter the function of finding fixpoints.	[F1]	[View FixPoint] 1/4 Job : JOB1 Pt. : 6 N : 1.000m E : 1.000m Z : 1.000m Find New Edit



6.2.2 Add Fix Pt.

Steps	Key	Display
-------	-----	---------





OK

(4) After finishing new a	آئر آئر	D • /	
fixpoint, the program	[New Fi	. xPoint	TOB1
makes the point plus 1	Job Pt.	•	1 001
automatically and you	Ν	:	100.000m
can continue to input	E	:	100.000m
other fix points, as shown	Ζ	:	100. 000m
in the picture on the right.	Dool	1744	OK
Press [F1] (Back) or	Back		UK
[ESC] to go back.			

6.2.3


[ESC] to go back.		
6.2.3 Edit Fix Pt. The function can edit	-	
Steps	Key	Display
(1) In the interface of View FixPoint, you can find the data of need to be edited by pressing the direction key of left or right or in the function of finding. If you want to change the job which the point needs to be edited, you can press [Job] to select the target job.		[View FixPoint] 7/22 Job : JOB1 Pt. : P7 N : 2.000m E : 3.000m Z : 1.000m Find New Edit ↓

(2) Press [F3] (Edit) to		
enter the interface of Edit		
Fixpoint. The screen		©
displays the point data.		
Input the new point's		
name and coordinate and		
press [ENT] to move the		
cursor to the next row.		
When the data doesn't		
need to be edited, you		S
can press [ENT] directly.		
(3) Press [F4] (OK) to save the edited data after finishing inputting. Program gives a prompt	[F4]	[Edit FixPoint] 7/22 Job : J0B1 Pt. : P7 N : 12.000m E : 13.000m Z : 5.000m
whether to overwrite or not and press [F4] (OK) to over right and save.		Back OK

6.2.4 Delete Fix Pt.

Delete the selected fixpoint from the job.

Steps	Key	Display
-------	-----	---------




	[View Fi	ixPoint]	7/22		
	Job Pt.	:		[0B1 P7 ●	
(3) The interface backs	N E	:	3.0)00m)00m	
to the previous menu.	Z	:	1. ()00m	
	Find	New	Edit	↓ /	6
	Delete	Job		⊬	Þ,

6.3 Meas. Pt.

The measurement data in the job can be searched, displayed, and part of them can be deleted.

6.3.1 View the measurement data

Steps	Key	Display
(1) In the menu of Job Manager, press [F3] to enter the function of Meas.PT.	[F4]	[Job Manage] 1/2 - F1 Job (1) F2 Fix Pt. (2) F3 Meas. PT (3) F4 Code (4) F1 F2 F3 F4



6.3.2 Delete measurement data

The not good and the repeating measurement data can be deleted.

The station data and the last piece of data in the data items can not be deleted.

Steps	Key	Display
-------	-----	---------

(1) After finding the measurement point data which need to be deleted, press [F1] to delete.	[F1]	[View Meas Pt] 1/28 Pt. 6 Job DEFAULT Type Meas. HA 226° 43′ 06″ VA 89° 26′ 11″ Date 2015.05.23 Delete Search
 2 The window of program prompts whether to delete or not. Press [F4] to make sure to delete and press [F1] to cancel the operation. 	[F4]	If delete data? Data cannot recover! No Yes
(3) After the data is deleted, the screen displays the next piece of data.	[F4]	[View Meas Pt] 1/27 Pt. : 6 Job : DEFAULT Type : Meas. HA : 226° 43′ 06″ VA : 89° 26′ 11″ Date : 2015.05.23 Delete Search

6.4 Code.

Here can make operations on the code library, such as new, finding and

deleting.

6.4.1 **Input Code**

Every code has a note and up to 8 characters attributes.

[View Co	ode] 1,	/5 🗸
Code	:	TREE 🔶
Note	:	
Info 1	:	GREEN
Info 2	:	
Info 3	:	
Info 4	:	
Find	New	Delete
on of code'	attributes	
of the code		
nal annotati	on	
ner editable	informati	on

GSI-The introduction of code' attributes:

Code: Name of the code

Note: Additional annotation

Info1: The other editable information

.

Info8: Other information

Steps	Key	Display
(1) In the menu of Job Manage, pressing [F4] to enter the function of Code.	[F4]	[Job Manage] 1/2 - F1 Job (1) F2 Fix Pt. (2) F3 Meas. PT (3) F4 Code (4) F1 F2 F3 F4


(2) In the interface of View Code, pressing [F2] to enter the function of new code.	[F2]	[View Code] 1/5 Code : Note : Info 1 : Info 2 : Info 3 : Info 4 : Find New
(3) Input the name of code and the code information in the interface of Input code.		[Input Code]CodeC1NoteLIGHTInfo 1LIGHTInfo 2Info 3Info 4OK
 After finishing inputting, press [F4] to save the code. Program makes the Code's name plus 1 automatically, and you can continue to input other code. If the inputted code name exists in the memory, the program will give a prompt of whether to 	[F4]	[Input Code]CodeC2NoteLIGHTInfo 1LIGHTInfo 2Info 3Info 4OK

- 258 -

overwrite	
-----------	--

6.4.2 View Code


Steps	Key	Display
(1) In the menu of Job Manage, pressing [F4] to enter the function of Code.	[F4]	[Job Manage] 1/2 - F1 Job (1) F2 Fix Pt. (2) F3 Meas. PT (3) F4 Code (4) F1 F2 F3 F4
(2) Press the direction key of left or right, you can view all codes one by one.		[View Code]1/5Code:TREENote:Info 1:GREENInfo 2:Info 3:Info 4:FindNewDelete



If there is no code	
matches the condition,	
the program will give a	
prompt.	\odot

6.4.3 Delete Code

Steps	Key	Display
 After entering the dialog of code function, press the direction key of left or right to delete the code which need to be deleted. You can also press the key of [Find] to find the corresponding code. 		[View Code] 1/5 Code : TREE ↔ Note : Info 1 : GREEN Info 2 : Info 3 : Info 4 : Find New Delete
(2) After finding the code need to be deleted, press [F4] and program will give a prompt whether make sure to delete.	[F4]	A: [View Code] 1/4 ↓ Code : C1↓ Note : LIGHT Info 1 : Info 2 : Info 3 : Info 4 : Find New Delete



6.5 Memory Statistics

Display the information of the memory usage and format the memory.

Format the memory can delete all data of job, code and road. The setting of application also can be reset, please operate carefully.

Steps	Key	Display
(1) In the menu of Job Manage, press [PAGE] and display the second page of the menu, press [F1] to enter the function of memory statistics.	[F1]	[Job Manage] 2/2 ^ F1 Mem.stat. (5) F1
(2) Press [F1] (Prop.) can view the properties of the disk, including free space.	[F1]	[Disk Info.]Disk Name :A:Local DiskDisk Space:2036KBUsed Space:66KBFree Space:1970KBFormatOK
(3) Press [F2] (Format) can format the disk, program will give a prompt to make sure to format or not, press [F4]	[F2]	Sure to format? Data cannot recover!
to make sure to format and press [F1 to cancel the operation.]		No Yes

7 Data Transfer

This function is doing data transmission between instrument and computer, or between instrument and removable device. This function includes 2 parts, import and export.


The data transmission between instrument and removable device must have U Disk plugged in.


Note: The machine supports up to 8G U disk read and write, when running the program, don't insert or pull out the U disk. If you pull out the U disk when the instrument checking it, the subsequent operations may cause error!


7.1 Data Import

User can use this function to transfer fixed points data or code data to instrument from computer via RS232 cable. User can also transfer fixed points data to instrument via U Disk.


Impo	ort:	Fixed Points, Code
Meth	od:	RS232, U Disk
Form	nat:	CASS, GTS-7, CSV, GSI(For U Disk)
Sour	ce:	Data file in U Disk (For U Disk)
Job:		Target job that data been transfer to.
Steps	Ke	Display
	у	







[F4]	
(Import)	
on the	
instrume	
nt.	
III.	
5 If	
choosin	
g U	
Disk	
method,	
pluggin	
g u disk	[Import Fix PT]
in the	
instrume	Mode IDisk () Source Imported:91 DB1
nt usb	Source (Imported:91)B1 Format : CASS Format ()
port	Target Job: DEFAULT
first,	
then:	Job Source Import
1. Press	
[◀],	
[▶] key	
to select	
"U	
Disk";	
2. Press	



import.		
6		
Import		®
code		[Import Code]
can only		Mode : RS232C ()
use	[F	Data Type : Code
RS232C	4]	
method.	-	
This is		
same to		Import
Step (4)		
•		

7.2 Data Export

User can use this function to transfer internal data (fixed points, measurement data, and code) from instrument to computer or u disk.

Export: Fixed points, measure data, and code.

Method: RS232C, U Disk.

Format: CASS, GTS-7 (For fixed point, U Disk)


HTF format, GSI format, GTS-7, CSV, CASS(For measure


data, U Disk)

Job: Job needs to export.

Steps	Key	Display
-------	-----	---------

		[Transfer]
		F1 Import Data (1)
(1) In main menu,	[4]	F2 Export Data (2)
choose "4 Transfer" to		
enter "Data Transfer"		
menu.		F1 F2
		[Export Data]
	(120)	F1 Job Data (1)
	[F2]	F2 Code Data (2)
Pressing [F2] or [2]	or [2]	
enters "Export Data"	[2]	
I		F1 F2
		[Job Data]
(2) In "Export Data"		Job : DEFAULT
	[F1]	Data Type : Meas. PT
menu, press [F1] or	or	Mode : RS232C↔
[1] entering "Export	[1]	
job data" function.		
		Job Export
/		





8 Instrument Setting

8.1 General Setting


In Setting Menu, choose "1 General" to enter "General Setting".


()			۱ <u> </u>		
Light	:	Low () 🗸	Hz increment:	Right () ⇔	
Trigger Key	:	DIST (V-Setting :	Zenith	
User Keyl	:	Level 🌗	Angle Unit :	° ′ ″ 🔶	
User Key2	:	NP/P 🔶	Min. Reading:	1″ 🌒	
Key Beep	:	On 🔶	Dist. Unit :	Meter ()	
Sector Beep	:	On 🚸	Dist.Decimal:	0.0001	
Tilt	:	Off 🔶	Temp. Unit :	°C 🌗	
Reset		OK	Reset	ОК	
		Press. Unit :	hPA 🔶 🔶		
		Code :	Permanent ()		
		Auto-Off :	Off ()		
		Port :	RS232C ()		
		Baudrate :	115200		
		Coord. type :	NEZ ()		
		Language :	English 🔶		
		Reset	OK	1	

Fields of General Setting

Field	Description
Light	High, Medium, Low, Off. 4 Levels of background light.
Contrast	1~9. Set the display contrast.
Trigger Key	Off: Disable trigger key.

	ALL: Dist and record.
	DIST: Only dist.
User Key 1	Configures \mathcal{A}_1 with a function from the FNC menu.
User Key2	Configures 2 with a function from the FNC menu.
Кеу Веер	The beep is an acoustic signal after each key stroke.
	On: Enable beep.
	Off: Disable beep.
Sector Beep	On: Sector Beep sounds at right $angles(0^{\circ}, 90^{\circ}, 180^{\circ},$
	270° or 0, 100, 200, 300 gon).
	Off: Sector Beep disabled.
Tilt	On: Biaxial compensation enable.
	Off: Tilting compensation disable.
	X Only: Single axis compensation enable.
Hz increment	Right: Set horizontal angle to clockwise direction measurement.
	Left: Set horizontal angle to counter-clockwise direction





	MIL Mil, 0 to 6399.99mil.
	The setting of the angle units can be changed at any time. The actual displayed values are converted according to the select unit.
Mini. Reading	Sets the number of decimal places shown for all angular
	fields. This is for data display and does not apply to data
	export or storage.
	°′″:1''/5''/10''
	Gon:0.0002/ 0.001 / 0.002
	Mil : 0.005 / 0.02 / 0.05
Dist. Unit	Sets the units shown for all distance and coordinate related
	fields.
	Meter Meters [m].
	US-ft US feet [ft].
	INT-ft International feet[fi].
	ft-in1/8 US feet-inch-1/8 inch [ft].
Dist. Decimal	Sets the number of decimal places shown for all distance
	fields. This is for data display and does not apply to data
	export or storage.

	3 Display distance with three decimals.					
	4Display distance with four decimals.					
Temp. Unit	Sets the units shown for all temperature fields.					
	°C Degree Celsius.					
	F Degree Fahrenheit.					
Press. Unit	Sets the units shown for all pressure fields.					
	hPA hecto-Pascal.					
	mmHg Millimeter mercury.					
	inHg Inch mercury.					
Code	Sets if the code will be used for one, or many, measurements.					
	Rec/Reset The code is cleared after ALL or REC.					
	Permanent The code remains after measurements.					
Auto-Off	30min Auto power off after 30min's no operation.					
	Off Disable auto-off.					

Port	RS232C Use serial port as communication interface.			
	Bluetooth Use Bluetooth as communication interface.			
	If instrument does not support Bluetooth, there will be no Bluetooth option here.			
Baudrate	Sets the serial port baudrate.			
	9600/19200/115200			
Coord. type	Sets the type of coord.			
	NEZ/ENZ			
Language	Changes the software's interface language.			

8.2 EDM Setting

See Chapter "3.2 EDM Setting".

9 Adjust and Tools

9.1 Adjust


Warning:


The following functions must be carried out under the guidance of professionals, if the operation is wrong, it may lead to the instrument can't work properly!


Through Main Menu \rightarrow "6 Tools" \rightarrow "1 Adjust", entering adjust menu,

Like


below







Input PIN code(82543), and then press key ENT, the instrument will be



turned off.

9.1.1 View adjust parameters

In Tools Menu, choose "1 Adjust", and then press [F1] to enter "View adjust parameters".

Parameters include Vert. I.E and tilt sensor parameters.

[View	Adjust	Param.]	
Vert.	I.E.:	93°	35' 52"
Xk	:		-0.8400
XO	:		9
Yk	:		1.000
YO	:		0
	_		OK


9.1.2 Adjust Index Error

In Tools Menu, choose "1 Adjust", then press [F2] to enter "Adjust Index Error".

Steps:

-				
Steps	Key	Display		
(1) After leveling the total station, aim at target with face left, then press [F4](OK).	[F4]	[Adjust Index Error] F1 reading: 342°11′59″ F2 reading: Vert. I.E.: Take reverse! OK		
(2) Aim at the same target with face right, and press [F4] (OK).	[F4]	[Adjust Index Error]F1 reading:342° 11′ 59″F2 reading:191° 26′ 31″Vert. I.E.:Take reverse!OK0K		

0




Note: If there is no special requirement, the compensator should be turned on before Index error correction.

9.1.3 Adjust Tilt X

Before compensating for the compensator, make sure that the indicator difference is recalibrated in accordance with 9.1.2 procedure in the closed compensator state.

First, place the instrument as picture shown below with collimator facing up. This will help screw A to adjust the inclination of the instrument.



In Tools Menu, choose "1 Adjust", and then press [F3] to enter "Adjust Tilt X".

These are the calibration of x-direction of compensator's vertical axis.

Steps	Key	Display
(1) Level instrument, focus on the reticle of collimator, record the vertical angle V0. Use fine tuning to set vertical angle to V0+3',focus on the reticle center accurately, wait for stable value, press [F4](OK).	[F4]	[Adjust Tilt X] HA : 10° 12′ 02″ VA : 81° 53′ 50″ Tilt : -117 F1 up 3′ OK
 (2) Use fine tuning to set the vertical angle to V0-3', focus on the reticle center accurately, wait for stable value, press [F4] (OK). (3) Use fine tuning to set the vertical angle as V0, focus on the reticle center accurately. 	[F4]	Adjust Tilt X] HA : 10° 12' 02" VA : 81° 59' 50" Tilt : -86 F1 down 3' OK

(4) Reverse the telescope, use face right to focus on the reticle of collimator, record the vertical angle V1.Use fine tuning to set the vertical angle as V1-3',focus on the reticle center accurately, wait for stable value, pressF4(OK).	[F4]	[Adjust Tilt X] HA : 190° 25' 38" VA : 269° 23' 45" Tilt : 96 F1 up 3' OK
(5) Use fine tuning to set the vertical angle as V1+3', focus on the reticle center accurately, wait for stable value, press [F4](OK).	[F4]	[Adjust Tilt X] HA : 342° 11′ 59″ VA : 269° 29′ 45″ Tilt : 91 F1 down 3′ OK

6 After finishing, it	[F4]	[Adjust	Tilt X	(]	
will display the results,		HA	:	342°1	1′ 59″
press [F4](OK), save		VA	:	269°2	9′46″
and back to menu.		Tilt	:		100
		Xk	33.08	59 XO: -	
					OK

Note: CoK (linear coefficient): If absolute value > 1.5, you need to re-calibrate; In the correction process by pressing the ESC key, will exit, holding compensator parameters unchanged.

9.1.4 Adjust Tilt Y

In Tools Menu, choose "1 Adjust", and then press [F4] to enter "Adjust Tilt Y".

These are the calibration of y-direction of compensator's vertical axis.

Steps	Key	Display
(1) Level instrument, focus on the reticle of collimator, record the vertical angle V0. Use fine tuning to set vertical angle to V0+3',focus on the reticle center accurately,	[F4]	[Adjust Tilt Y] HA : 10° 12′ 02″ VA : 81° 53′ 50″ Tilt : -117 F1 up 3′ OK

then turn the instrument counterclockwise 90 $^{\circ}$, wait for stable value, press [F4](OK) ,and then turn 90 $^{\circ}$ clockwise back to the original direction.		S
 (2) Use fine tuning to set the vertical angle to V0-3', focus on the reticle center accurately, then turn the instrument counterclockwise 90°, wait for stable value, press [F4] (OK) ,and then turn 90° clockwise back to the original direction. (3) Use fine tuning to set the vertical angle as V0, focus on the reticle center accurately. 	[F4]	Adjust Tilt Y] HA : 10° 12′ 02″ VA : 81° 59′ 50″ Tilt : -86 F1 down 3′ OK

(4) Reverse the		[Adjust Tilt Y]
telescope, use face right		HA : 190° 25′ 38″
to focus on the reticle of		VA : 269° 23′ 45″
collimator, record the		Tilt : 96
vertical angle V1.Use		
fine tuning to set the		F1 up 3'
vertical angle as	[F4]	ОК
V1-3', focus on the	[1]+]	
reticle center accurately,		
then turn the instrument		
counterclockwise 90 °,		
wait for stable value,		4
pressF4(OK) ,and then		
turn 90 ° clockwise back		
to the original direction.		
(5) Use fine tuning to		[Adjust Tilt Y]
set the vertical angle as		HA : 342° 11′ 59″
V1+3', focus on the	[F4]	VA : 269° 29′ 46″
reticle center accurately,		
then turn the instrument		Tilt : 91
counterclockwise 90 °,		F1 down 3'
wait for stable value,		OK
press [F4](OK).		

6 After finishing, it	1541	[Adjust Tilt Y]
will display the results,		HA : 342° 11′ 59″
press [F4](OK), save		VA : 269° 29′ 46″
and back to menu.	[F4]	Tilt : 100
		Xk: 33.0859 X0: -55
		ОК


Note: CoK (linear coefficient): If absolute value > 1.5, you need to re-calibrate; In the correction process by pressing the ESC key, will exit, holding compensator parameters unchanged.

9.1.5 Adjust Tilt Zero

In Tools Menu, choose "1 Adjust", then press [F4] +[F1] to enter "Adjust Tilt Zero".

Steps:

Steps	Key		Display
(1) After leveling the total station, aim at target with face left, then press [F4](OK).	[F4]	[Adjust Tilt X: Y:	



Note: If there is no special requirement, the compensator should be turned on before Index error correction.

9.1.6 Adjust Haxis err

Follow the operation process below:

Operation process	Key	display
(1) Place the instrument		
on the test table and level		
the instrument.		

(2) In setting mode, "2.	"2.	Adjust Haxis err
Instrument para." then	Instrument	HR: 244° 06′ 10″
press [ENT], go to	para."	
machine parameter setting	+	Aim upper tube F1
menu. Then choose "8.	"8. Adjust	
Adjust H axis Err".	H axis Err"	ENT
(3) After entering, it will	【ENT】.	Adjust Haxis err 🛛 🛞 🕮 🛈
prompt "F1 up", and let	[F4]	
positive scope aim at the		HR: 244° 06′ 10″
target, when the reading is		Aim upper tube F1
stable, press [ENT] or		
【F4】 to confirm.		ENT
(4) According to the	【ENT】.	Adjust Haxis err
prompt "F1 down", and let	【F4】	
positive scope aim at the		HR: 244° 06′ 10″
target, when the reading is		Aim down tube F1
stable, press [ENT] or		
[F4] to confirm.		ENT
(5) Rotate the instrument	【ENT】.	Adjust Haxis err
counterclockwise by 180°.	F4	
According to the prompt		HR: 244° 06′ 10″
"F2 up", let the reverse		Aim upper tube F2
scope aim at the target.		
After the reading is stable,		ENT
press [ENT] or [F4] to		
confirm;		
	1	1

(6) According to the	[ENT].	Adjust Haxis err
prompt "F2 down", let the	F 4	HR: 244° 06′ 10″
reverse scope aim at the		IIK. 244 00 10
target. After the reading is		Aim down tube F2
stable, press [ENT] or		
[F4] to confirm;		ENT
(7) After finishing all	[ESC]	
steps, the instrument will		
save the parameter. During		
the calibration process,		
press the 【ESC】 key to		
exit the calibration.		

Note: If the calibration result is over 60'', the instrument needs to be calibrated again, otherwise it will cause the measurement results to be wrong.

9.1.7 Adjust collimate err

Follow the operation process below:

Operation process	Key	Display
(1) Place the instrument		
on the test table and level		
the instrument.		
(2) In setting mode, "2.	"2.	Adjust collimate err 💲上 🕼 🚺
Instrument para." Then	Instrument	HR: 244° 06′ 10″
press [ENT], go to machine	para."	HR: 244 00 10
parameter setting menu.	+	Take positive
Then choose "9. Ad.	"9. Ad.	
Collimate Err".	Collimate	ENT

	Err"	
(3) Enter the collimation	【ENT】.	Adjust collimate err 🛞 🕮 🕅
correction function, and the prompt displays "Take	【F4】	HR: 244° 06′ 10″
positive", then let the positive scope aim at the		Take positive
target. After the angle value		ENT
is stable, press [ENT] or [F4] to confirm;		
(4) Rotate the instrument	【ENT】.	Adjust collimate err 🛞 🖄 🚺 🚺
by 180°, and the prompt displays "Take reverse", then let the reverse scope aim at the target. After the angle value is stable, press 【 ENT 】 or 【 F4 】 to confirm; (5)When all process done, the instrument will save all parameters. During the calibration process, press the "ESC" key to exit the	[F4]	HR: 244° 06′ 10″ Take reverse ENT

Note: If the calibration result is over 60'', the instrument needs to be calibrated again, otherwise it will cause the measurement results to be wrong.

9.1.8 Instrument constant setting

In Tools Menu, choose "1 Adjust", and then press [F4] to enter "Const. Setting".

Press [F4](OK) to save after editing the constants.

[Const. Setting	g]
Add Const. :	-9
Mul. Const.:	0
	OK

9.1.9 Factory setting

In Tools Menu, choose "1 Adjust", and then press [5] to enter "Factory Setting".

If you need to reset the instrument parameters to factory state, you can use this function, press key [F4] (Yes) and then the instrument will auto power off.

9.2 System information

9.2.1 View System Information

In Tools Menu, choose "2 Info." to enter "Info".

In this window, user can view detail information about the instrument, includes instrument type and SN, firmware version and date time.

	[]	nfo.]
Inst.No.	:	648164
FW. Ver.	:	V1.0(20151103)
EDM.Ver.	:	F122RL:8.6h
Time	:	13:42:28
Date	:	2015.11.12
Date	Time	Upgrade Back


System Information

9.2.2 Set System Date

In system information window, press [F1] (Date) to enter "Date Setting" window.

To set the date, input the new date string that in the format of tips, then press [F4] (OK) to save the new date.

For example: To set date "2015-11-11", input string "20151111", then press [F4] (OK) to save.



Date Setting

9.2.3 Set System Time

In system information window, press [F2] (Time) to enter "Time Setting"

window.

To set the time, input the new time string that in the format of tips, then press [F4] (OK) to save the new time.

For example: To set time"13:58:30", input string "135830", then press [F4] (OK) to save.

[Time Setting]
Time(24h): 13:58:30
Input as 'hhmmss'
Back
Dack



9.2.4 Firmware Upgrade

Warning:

The following functions must be carried out under the guidance of professionals, if the operation is wrong, it may lead to the instrument can't work properly!

This function is prepared for the users to upgrade the instrument software.

1. Input PIN code(82543), and then press key ENT, the instrument will be turned off.

[FW.	Upgrad	e]			
PIN	:				
Bacl	K			OK	

 Connected to the computer through a serial cable, after installing the correct driver premise, open a HyperTerminal software, configure the correct serial port, it will "bits / sec" is set to 115200, "Data Flow Control" is set to "None" and press OK.

	COM3 Properties
	Port Settings
1	Bits per second: 115200
1	Data bits: 8
	Parity: None
	Stop bits: 1
	Flow control: None
/	Restore Defaults
	OK Cancel Apply

3. Press the power key of the instrument in Hyper Terminal, shown as

follows:

Note: Software upgrade operation must be careful once you select the instrument into the upgrade status; if press "3" in the picture below, you can also resume running the previous program.

🗞 update - HyperTerminal 📃 🗆 🔀	
File Edit View Call Transfer Help	
0 🗳 🖉 🕉 = 0 🗃 🖆	
SUNWAY CO.LID SUZHOU CHINA SUNWAY CO.LID	
CONNECTED 0100100 HILL 010101 HILL 01010 HILL 010	

4. Press 1 button on the keyboard into waiting to send program state, and

then select "send file".

🗞 update - HyperTerminal	
File Edit View Call Transfer Help	
Capture Text Send Text Fie	1^
Capture to PrinterNWAY_CO.LTD_SUZHOU_CHINA =	
Total station boot loader	
=ver 0.1 R&D =	
Program -> Total station (Download)	
Sends a file to the remote system	.;

5. Select the new edition total station software, click on "send" button.


Send File	
Folder: F:\	
Filename:	
F:\hts220V1.1.bin Browse	
Protocol:	
Ymodem	1 9
Send Close Cancel	5


6. It will display the sending application process, and then close the super terminal, starting up after removing the instrument battery and then putting in again. The current software is the new version updated previously.

9.3 Checkout and calibration

The instrument at the factory has to undergo a rigorous inspection and correction, meeting the quality requirements. However, after long transport or environmental change, its internal structure will be some impact. Therefore, the new purchased instruments should be checked and calibrated before surveying to ensure the precision.

9.3.1 Tube level





Checkout

Refer to the chapter "Leveling instrument accurately by tube level" of "Setting up the instrument"

Calibration

- 1. In the calibration, if the leveling bulbs diverge from the center, use the foot spiral which parallels the leveling tube to adjust to make the bubble move half of the distance to the center. For the remaining, use the calibration needle to turn the level calibration screw (in the right of the water-level) to adjust the bubble to the center.
- 2. Turn the instrument for 180 °, check that whether the bubble is in the center. If the bubble is not centered, repeat Step (1) until the bubble to the center.
- 3. Turn the instrument for 90°, use the third foot screw to adjust the bubble to the center.
- Repeat the Steps of checkout and calibration until the bubble in the center in every direction.

9.3.2 Circular level

Checkout

After the level tube calibrated correct, if the circular level bubble also in the center, so there is no need to calibrate

Calibrtion


If the bubbles is not in the center, use the correction needle or six angle wrench to adjust the correction screw which under the bubble to make the bubble to the center. For calibration, you shall first loosen the calibration screw (1 or 2) which opposite to the direction of the bubble offset, then tighten the other correction screw in the offset direction to make the bubble in the center. When the bubble is in center, make sure the pressures of the three calibration screws are consistent.

9.3.3 Telescope reticle

Checkout


After leveling the instrument find a target A with the telescope, make the center of the crosshair focused on target A and fixed horizontal and vertical brake hand wheel.

- 1. Rotate telescope vertical micrometer hand wheel, move A point to the edge of the field of view (A 'points).
- 2. If A moves along the vertical line of the crosshair, but A point is still in the vertical line, as the left picture, the crosshair doesn't need to calibrate. If A point deviate from vertical line center, as the right pictured, the crosshair is slant, so need to calibrate the reticle.



Calibration

- 1. First, take down the reticle cover between telescope eyepiece and focusing hand wheel, and you can see four fixed screw of the reticle bed (sees attached figure).
- 2. Unscrew the three fixed screw evenly with screwdriver, rotate the reticle around collimation axis, to make A point on the vertical line of the reticle.
- 3. Tighten the screw evenly, test the calibration results with the above methods.
- 4. Put the protective cover back.



9.3.4 The verticality of collimation axis and horizontal axis(2C)

Checkout

1. Set a target A in about 100m away, and make sure the vertical angle of the

target is within \pm 3 °. Precisely level the instrument and switch on it.

2. Make the telescope focused on target A in face left, and read the horizontal angle.

For example: horizontal Angle $L = 10^{\circ}13$ '10".

3. Loosen the vertical and horizontal brake hand wheel, turn the telescope, rotate the alidade to face right and focus on the same target A. Before aiming please tighten the horizontal and vertical brake hand wheel and read the horizontal angle.

For example: level Angle $R = 190^{\circ}13$ '40".

4. $2 \text{ C} = \text{L-}(\text{R} \pm 180^{\circ}) = -30 \text{ "} \ge \pm 20$, need to calibrate.

Calibration

1. Use the horizontal micrometer hand wheel to adjust the horizontal angle to the right reading which has eliminated the C.

R + C = 190°13 '40 "-15 "= 190°13' 25"

- 2. Take down the reticle bed cover between the telescope eyepieces and focusing hand wheel, adjust the calibration screw of the crosshair on the left and right. First, loosen the screw on one side, and screw up the screw on the other side, move the reticle and focus on target A.
- 3. Repeat the test Steps, calibrate it to | 2 C | < 10.
- 4. Tighten the calibration screws, put the protective cover back.

four adjusting screws



Notice: Check the photoelectric coaxiality after calibrating.

9.3.5 Vertical plate index zero automatic compensation

- Checkout
- 1. Set up and level the instrument, make the direction of the telescope consistent with the line between the center of the instrument and any of the foot screw.
- 2. The vertical plate index change to zero after switching on, tighten the vertical brake hand wheel, the instrument display the current telescope vertical angle.
- 3. Slowly rotate feet X to 10 mm around in one direction, the display of the vertical Angle will change from changing until disappear to appear "compensation beyond!" correspondingly, it indicate that the dip angle of the vertical axis is bigger than 3 ', beyond the range of vertical plate compensator design .When rotating the feet spiral recovery in the opposite direction, instruments shows vertical Angle again, if you can see the change when testing it again and again in critical positions, it says that

vertical plate compensator works normally.

Calibration

When you find that instrument compensation is useless or abnormal, it should be sent to the factory for checking.

9.3.6 Vertical collimation error (I Angle) and vertical collimation zero value setting


Checkout

- 1. Boot after settling and leveling the instrument, focus the telescope on a clear goal A, get the face left reading of vertical Angle L.
- 2. Turn the telescope to aim A and get the reading R for face right.
- 3. If the vertical zenith angle is 0 °, then i = (L + R-360 °) / 2, if the vertical Angle level is 0. Then i = (L + R-180 °) / 2 or (L + R-540 °) / 2.
- 4. If $|i| \ge 10^{\circ}$, may be you need reset the zero value of vertical index.
- 5. Operation refers to chapter "Adjust index error". Note: repeat the checkout steps to retest the index error again (i Angle). If the index error still can not accordance with requirements, it should check the three Steps of calibration index zero setting (in the course of zero setting ,the vertical angle showed is not compensated and corrected, it is just for reference) to see whether it is incorrect, whether the focusing of target is correct, reset according to the requirements.
- 6. If it still can not accordant with the requirements after repeated operation, it should be sent to the factory for checking.

9.3.7 Plummet

Checkout

- 1. Set up the instrument to the tripod, draw a cross on a white paper and put it on the ground below the instrument.
- 2. Adjust the focal length of the optical plummet (for the optical plummet) or switch on laser plummet, move the white paper to make the cross in the center in the field of view (or laser flare).
- 3. Turn the feet screw, make the center mark of the plummet coincide with the cross center.
- 4. Rotate alidade, every turn of 90 °, observe the contact ratio of the optical plummet and cross center.
- 5. When rotate the alidade, the center of the optical plummet always coincide with the cross center, there is no need to calibrate. Otherwise you should calibrate as the following methods.
- Calibration
- 1. Take down the screw cover between the optical plummet eyepiece and the focusing hand wheel.
- 2. Fix the white paper with a cross, and mark the points when the instrument rotates 90°, as the figure shows A, B, C, D points.
- 3. Connect the diagonal points A、C and B、D with a straight line, the intersection name of the two line is O.
- 4. Use the calibration needle to adjust the four calibration screw, to make the center mark of the plummet coincide with point O.



- 5. Repeat Step 4, check and calibrate until it meet the requirements.
- 6. With the laser plummet, unbolt the laser cover, using 1 # hex wrench to adjust the three screws, fasten one side and loosen the other side, and adjust the laser flare to point O.
- 7. Put the cover back in place.

9.3.8 Instrument additive constant (K)

The instrument constant is inspected when it out, and correct it inside the machine, make K = 0. Instrument constant change rarely, but we suggest that check it this way for one or two times each year. The checkout should be done in the standard baseline, or you can take the following simple method.

Checkout

- Choose a flat field A to set up and level the instrument, mark three points A、B、C in the same line ,their interval is 50m, and set up the reflection prism accurately.
- 2. After setting the temperature and pressure data, accurately measure the horizontal distance of AB, AC.
- 3. Setting up and centering the instruments accurately, measure the horizontal distance of BC accurately.
- 4. You can get the instrument ranging constant:

K = AC - (AB + BC)

K should be close to 0, if |K| > 5 mm, it should be send to standard baseline field for strict checking, then calibrate it based on the checking value.

Calibration

If it turns out the instrument constant does not close to 0 but changing

after strict inspection, you need to calibrate it, set the instrument additive constant according to the comprehensive constant K value. Such as: the K has been measured as -5 according to the method above, and the original instrument constant is -20, so the new value should be set as -20-(5) = -15; Input-15 through "menu-> 6-> 3" and then confirm.

- Use the vertical line of the reticle to orientate, make A, B and C at the same line accurately. There must be a clear mark for point B the ground to focus on.
- Whether the prism center of B coincide with the instrument centers is the guarantee of checking the accuracy, so, you had better use tripod and all-purpose tribrach, for example, if you change the three hand type prism connector with tribrach, keep the tripod and tribrach stable, just change the prism and the part above tribrach of instrument, and it can reduce the error of misalignment.

9.3.9 The parallelism of collimation axis and photoelectricity axis

- Checkout
- 1. Set up the reflecting prism 50 meters long from the instrument.
- 2. Focus on the reflecting prism center with telescope crosshair accurately.
- 3. Open EDM signal, observe maximum value of the signal, and find the center of the launch axis.
- 4. Check whether the telescope crosshair center coincide with the emission photoelectricity axis center, if they coincide on the whole we can say it qualified.
- Calibration

If the telescope crosshair center deviates from emission photoelectricity axis center largely, send it to professional repair and calibration department.

9.3.10 No prism ranging

The red laser beam is coaxial with the telescope, used for no prism ranging, and it is sent by telescope. If the instrument has been calibrated, red laser beams will coincide with the line of sight. External influence such as the vibration, the larger temperature change and other factors may make laser beam and viewing not overlap.

Before precise ranging, you should check whether the direction of the laser beam is coaxial. Otherwise, it could lead to inaccuracy.

Warning:

Looking straightly at the laser is dangerous.

Prevention:

Don't look laser beams directly, or focus on others.

Checkout

Put the gray side of the reflector towards the instrument, and put it 5 meters and 20 meters away. Start laser direction function. Focus on the reflector center by the telescope crosshair center, and then check the position of the red laser point. Generally speaking, the telescope is equipped with special filter, human eyes can't see laser point through the telescope, you can see the offset between the red laser point and the reflector crosshair center, you can observe this above the telescope or at the side face of reflector . If laser center coincide with the crosshair center, it indicate that the adjustment meet required accuracy. If the offset between the points position and the mark of crosshair is out of limitless, it need to send it to professional department for adjustment.

10 Technical parameters

Function			Configuration	
		Unit	SLT10	
		Telescope		
Imaging			Erect	
Magnification		×	30	
Field of view			1 °30′	
Min. target distar	ice	m	1.5	
Effective aperture		mm	40/50(EDM)	
	Angl	e measuremer	nt(Hz, V)	
Angle measurement accuracy		(″)	2.0	
Angle measurement method		—	Absolute encoder	
Minimum reading		(")	1	
	Distan	ce measureme	ent (IR)	
Range	Single prism	km	5	
	Triple prism	km	6	
	No-prism ¹	m	1000	
Time	Repeated	S	0.5	
	Tracking	S	0.3	
Minimum Display		mm	0.1	
Accuracy	Prism	mm	$\pm (2 + 2 \times 10^{-6} \text{D})$	
	No-prism		$\pm (3 \pm 2 \times 10^{-6} \text{D})$	

	Tilt compensa	ator
Compensation method	_	Biaxial type
Compensation range	(')	± 3
Communication port		R\$232C
U disk interface		YES
Bluetooth	—	YES
Temperature and pressure sensors	_	YES
	Display	
Screen	—	Both sides (320*240, Colorful)
Illumination	—	Support
	Laser Plum	b
Laser (optional) Laser Plumb	-	Wavelength 635nm Maximum output power (adjustable): not less than 0.4 mW, not more than 1.0 mW
	level	
Tubular Level	(") /2 mm	30
Round level	(') /2 mm	8
Built-in applications		Support
/	Battery supp	ly
Туре		Rechargeable High-energy lithium battery
Voltage	V	7.4

Power		W	< 2.2
Battery ca	pacity	mAh	3000
Working	Dist Angle	h	8 (At + 20 ° C, dist once per
duration	Dist + Angle	п	30s and keep measuring Angle)

1. It means good meteorological conditions (visibility not less than 30km), Target is KODAK CAT NO.E1527795 (90% reflective surface).

11 Attachment A File transfer format description (local format)

These following examples to instruct exported file format

STA	ST001,1.205,AD
XYZ	100.000,100.000,10.000
BS	BS001,1.800
HVD	98.2354,90.2314,10.235
SC	A1,1.800,CODE1
NEZ	104.662,99.567,10.214
SD	A2,1.800,CODE1
HVD	78.3628,92.4612,4.751
SA	A3,1.800,CODE1
HV	63.2349,89.2547

Each record consists of two rows:

The information in the first line of which is parsed as: record type, point name,

elevation, code

Such as:

STA refers to station point

BS refers to back sight

SC refers to coordinate data

SD refers to distance measurement data

SA refers to Angle measurement data

The second line information: data types, data records

Such as:

NEZ refers that the following data are coordinates with the order "NEZ"

ENZ refers that the following data are coordinates with the order "ENZ"HVD refers that the following data are horizontal Angle and vertical Angle and slope distance

HV refers that the following data are horizontal Angle and vertical Angle



Satlab Geosolutions AB

www.satlabgps.com

ADD: SE-436 32 Askim,SWEDEN E-mail: info@satlabgps.com